2/9/22, 12:27 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21011986/ERA3Q2

Date: 09/02/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0001784

Claimant Vehicle No: SKU2627M Insured Vehicle No: GBK5918M

Date of Loss: 24/11/2021 Nature of Claim: TP Claim No: MCV2021D0005134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU2627M

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520296637

Reg. Date: 14/07/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0313365

Colour: White Odometer: 114320 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,880.00	1,112.00	768.00	40.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	460.00	250.00	35.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,590.00	1,572.00	1,018.00	39.31
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	2,590.00	1,250.00	1,340.00	51.74
+ GST 7.00/7.00% (S\$)	181.30	87.50	93.80	51.74
Nett Amount (S\$)	2,771.30	1,337.50	1,433.80	51.74
+ Loss of Use (5.0 x S	\$60.00/day) (S\$)	300.00		
+ Doc/Search Fee (S\$)		7.45		
N	ett Liability (S\$)	1,644.95		

INSPECTION

Date of Assignment: 25/11/2021

Date Inspected: 26/11/2021 Inspected At: 38 Woodlands Industrial Park E1, #05-18

Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

2/9/22, 12:27 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2022)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU2627M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Broken	1,080.00 F	*1,080.00 FL
2	10	*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
3	1	*REAR BUMPER RETAINER RH	Not Necessary	40.00 F	*-FL
4	1	*REAR BUMPER BRACKET RH	Not Necessary	50.00 F	*- FL
5	1	*REAR BUMPER TOW EYE COVER	Crushed	30.00 F	*30.00 FL
6	1	*END PANEL	Not Necessary	380.00 F	*- FL
7	1	*REAR BUMPER REFLECTOR RH	Not Necessary	50.00 F	*- FL
8	1	*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
F=Fra	nchise part. S=SpcN	ett. L=ListItemDisc.	_		
			Sub Total (S\$)	1,880.00	1,340.00
		- List Item Discount of	on L Items 0.00/20.00% (S\$)	0.00	228.00
			Total Parts (S\$)	1,880.00	1,112.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	SPRAY PAINTING WHOLE REAR BUMPER	New	300.00	200.00		
2	REMOVE,REPLACE AND REFIT REAR AFFECTED AREA	New	300.00	200.00		
3	REMOVE,REPLACE AND REFIT REAR BUMPER REVERSE SENSOR	New	80.00	30.00		
4	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00		
	Gross Labour Cost (S\$)		710.00	460.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >