

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21011988/EQF3E2

Date: 12/05/2022

REFERENCE

Insured/Claimant: NG JOO HEAN Policy No: D20MPC0006006_01
Date of Loss: 20/11/2021 Nature of Claim: OD Claim No: MPC2021D0005074

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV6771Z**
Make & Model: MERCEDES-BENZ GLA180, 1.3 PROGRESSIVE (A) Engine No: 27091031922405
Reg. Date: 30/09/2020 (Man. Year: 2019) Chassis No: WDC1569422J668592
Colour: Black Odometer: 16512 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$134,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,278.00	7,448.40	1,829.60	19.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,030.00	1,940.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,248.00	9,478.40	3,769.60	28.45
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,648.00	8,878.40	3,769.60	29.80
+ GST 7.00/7.00% (S\$)	885.36	621.49	263.87	29.80
Nett Amount (S\$)	13,533.36	9,499.89	4,033.47	29.80

INSPECTION

Date of Assignment: 25/11/2021

Date Inspected: 25/11/2021 Inspected At:

Estimated Period of Repair: 5.0 days

AutoSprint Pte Ltd (HQ)
24, Leng Kee Road, #07-01/02 Leng Kee
AutoPoint
Singapore 159096

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV6771Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/H DOOR MIRROR	Cut	920.00 F	*920.00 FL
2	1		*L/H FRONT DOOR	Dented	1,598.00 F	*1,598.00 FL
3	1		*L/H REAR DOOR	Dented	1,730.00 F	*1,730.00 FL
4	1		*L/H REAR WHEEL ARCH GARNISH	Cut	200.00 F	*200.00 FL
5	1		*L/H REAR WHEEL SPORT RIM	Cut	830.00 F	*830.00 FL
6	1		*L/H REAR KNUCKLE ARM	Bent	1,200.00 F	*1,200.00 FL
7	1		*L/H REAR KNUCKLE ARM BEARING	Necessary	344.00 F	*344.00 FL
8	1		*L/H REAR UPPER ARM	Not Necessary	140.00 F	*- FL
9	1		*L/H REAR LOWER ARM	Not Necessary	185.00 F	*- FL
10	1		*L/H REAR SHOCK ABSORBER	Not Necessary	467.00 F	*- FL
11	1		*L/H REAR CONTROL ARM	Not Necessary	150.00 F	*- FL
12	1		*L/H REAR DOOR RUBBER	Necessary	265.00 F	*265.00 FL
13	1		*L/H LOWER SIDE SKIRTING	Cut	1,189.00 F	*1,189.00 FL
14	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
					Sub Total (\$\$)	9,278.00 8,276.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 827.60
					Total Parts (\$\$)	9,278.00 7,448.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REPLACE / REPAIR DAMAGED PARTS	New	1,600.00	900.00
2	LABOUR TO TRANSFER BOTH DOORS GLASS, REGULATOR & LOCK MECHANISM TO NEW REPLACE DOORS	New	400.00	160.00
3	TO SPRAY PAINTING ON THE AFFECTED PARTS & AREAS	New	1,200.00	660.00
4	LABOUR CHARGE TO REMOVE & REPLACE L/H REAR UNDERCARRIAGE DAMAGED PARTS	New	600.00	200.00
5	TO CHECK / ADJUST WHEEL ALIGNMENT	New	120.00	60.00
6	LABOUR CHARGE TO RECONNECT WIRE HARDNESS ON REPLACE PARTS	New	50.00	50.00
Gross Labour Cost (\$\$)			3,970.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >