

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011993/EUY3N2**Date:** 15/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00001112100

Claimant Vehicle No : SNA9041B**Insured Vehicle No :** GBH1205D

Date of Loss: 07/11/2021

Nature of Claim: TP

Claim No: SNM21D206406/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA9041B**

Make & Model: BMW 520I, 2.0 ADAP LED HL (A)

Engine No: 14706429B48B20A

Reg. Date: 22/07/2021 (Man. Year: 2021)

Chassis No: WBA72AG070WX35489

Colour: Black

Odometer: 4226 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R19

Rear Tyre Size: 245/40R19

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,038.65	4,840.45	198.20	3.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,626.00	4,478.00	148.00	3.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,664.65	9,318.45	346.20	3.58
+ GST 7.00/7.00% (S\$)	676.53	652.29	24.24	3.58
Nett Amount (S\$)	10,341.18	9,970.74	370.44	3.58

INSPECTION

Date of Assignment: 27/11/2021

Date Inspected: 29/11/2021

Inspected At:

Performance Motors Limited (HQ)
303 Alexandra Road, Singapore
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2021)
Parts:	143	BMW 520I 2.0 ADAP LED HL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA9041B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ALUMINIUM	Dented	1,758.45 FS	*1,758.45 FS
2	1		*REAR BUMPER CARRIER	Dented	582.55 FS	*582.55 FS
3	1		*REAR BUMPER TRIM STRIP (LUXURY)	Not Necessary	63.45 FS	*- FS
4	1		*REAR BUMPER BOTTOM TRIM PANEL	Broken	309.95 FS	*309.95 FS
5	1		*REAR BUMPER BOTTOM REINFORCEMENT	Broken	86.30 FS	*86.30 FS
6	1		*REAR BUMPER TRIM PANEL (PDC/PMA)	Broken	1,627.25 FS	*1,627.25 FS
7	1		*LETTERING 520I	Not Necessary	64.75 FS	*- FS
8	1		*TAIL LIGHT	Cut	390.25 FS	*390.25 FS
9	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
10	2		*EXPANDING NUT	Necessary	5.70 FS	*5.70 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **5,038.65** **4,840.45**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,BOOT LID AND ATTACHMENTS	New	1,700.00	1,700.00
2	TO PAINTING REAR BUMPER AND BOOT LID	New	1,923.00	1,826.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
Gross Labour Cost (\$\$)			4,626.00	4,478.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >