

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011994/EQY3N2**Date:** 02/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00027762100

Claimant Vehicle No : SMP8316Z**Insured Vehicle No :** SCF3438J

Date of Loss: 20/11/2021

Nature of Claim: TP

Claim No: SNM21D206808/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP8316Z**

Make & Model: HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)

Engine No: G4LDKD073685

Reg. Date: 18/10/2019 (Man. Year: 2019)

Chassis No: TMAH3513VLJ115227

Colour: White

Odometer: 47464 km

Engine Capacity: 1353 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,574.00	2,574.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	600.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,174.00	3,174.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	222.18	222.18	0.00	0.00
Nett Amount (\$\$)	3,396.18	3,396.18	0.00	0.00

INSPECTION

Date of Assignment: 30/11/2021

Date Inspected: 30/11/2021

Inspected At:

Komoco Motors - (alexandra) (HQ)
253 Alexandra Road
Singapore 159936

Estimated Period of Repair: 3.0 days

Adjuster: SHIAU CHAN**Manager:** CHEN TSUE YEE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
Parts:	144	HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8316Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*FRONT BUMPER CLIP	Necessary	12.00 FL	*12.00 FL
2	6		*UPR GRILLER COVER CLIP	Necessary	3.60 FL	*3.60 FL
3	1		*LAMP ASSY-HEAD,RH	Cut	3,201.90 FL	*3,201.90 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	3,217.50
					- List Item Discount on L Items 20.00/20.00% (S\$)	643.50
					Total Parts (S\$)	2,574.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIR (TO RENEW HEAD LAMP & RE-ALIGN FRT BUMPER)	New	320.00	320.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (TO RESPRAY FRT BUMPER)	New	280.00	280.00
Gross Labour Cost (\$\$)			600.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >