

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011995/UQY3N2**Date:** 09/12/2021REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00124252000

**Claimant Vehicle
No :** GBC9606D**Insured Vehicle
No :** GBC6640C

Date of Loss: 23/11/2021

Nature of Claim: TP

Claim
No: SNM21D206803/C2/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC9606D**

Make & Model: FIAT DOBLO, 1.2 D 1.3M (M)

Engine No: 198A30007077599

Reg. Date: 19/03/2014 (Man. Year: 2014)

Chassis No: ZFA26300006141655

Colour: White

Odometer: 103572 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: KAPSEN 7 mm

Rear Left Side: KAPSEN 7 mm

Front Right Side: KAPSEN 7 mm

Rear Right Side: KAPSEN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,541.20	4,980.38	9,560.82	65.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,070.00	1,830.00	46.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,441.20	7,050.38	11,390.82	61.77
Approved Total (Overridden) (\$\$)		5,600.00		
Nett Amount (\$\$)	18,441.20	5,600.00	12,841.20	69.63

INSPECTION

Date of Assignment: 25/11/2021

Date Inspected: 26/11/2021 Inspected At:

 8 KAKI BUKIT AVENUE 4
 #01-49 PREMIER @ KAKI BUKIT
 SINGAPORE 415875
 REPAIRER: 1ST AUTO PRO PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2021)
Parts:	M1-MPV	FIAT DOBLO 1.2 D 1.3M (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC9606D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent/Buckled	1,080.00 FL	*1,067.55 FL
2	1		*BONNET INSULATOR	Not Necessary	166.00 FL	*- FL
3	1		*BONNET HINGE LH/RH	N/s Bent	338.00 FL	*135.00 FL
4	1		*BONNET LOCK	Not Necessary	209.00 FL	*- FL
5	1		*FRONT BUMPER	Distorted	1,095.00 FL	*855.30 FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	184.00 FL	*68.00 FL
7	1		*FRONT BUMPER SIDE COVER LH	No such part	119.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	459.00 FL	*459.00 FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	361.00 FL	*- FL
10	1		*FRONT RADIATOR GRILLE	Not Necessary	339.00 FL	*- FL
11	1		*FRONT RADIATOR GRILLE LOGO	Not Necessary	149.00 FL	*- FL
12	1		*FRONT TOW COVER	Not Necessary	156.00 FL	*- FL
13	1		*FRONT BUMPER SPONGE	Torn	119.00 FL	*117.00 FL
14	1		*FRONT FENDER LH	Buckled	683.00 FL	*683.00 FL
15	1		*FRONT FENDER INNER SHIELD LH	Torn	249.00 FL	*249.00 FL
16	1		*FRONT SUPPORT PANEL	Dented/Twisted	784.00 FL	*645.10 FL
17	1		*FRONT SUPPORT PANEL INNER GARNISH	No such part	133.00 FL	*- FL
18	1		*FRONT HEADLAMP LH	Cracked	1,349.00 FL	*658.70 FL
19	1		*BATTERY	Serviceable	568.00 FL	*- FL
20	1		*ABS PUMP	Not Necessary	1,189.00 FL	*- FL
21	1		*ABS PUMP CABLE	Not Necessary	317.00 FL	*- FL
22	1		*FUEL BOX	Cracked	746.00 FL	*485.00 FL
23	1		*WASHER TANK	Not Necessary	309.00 FL	*- FL
24	1		*AIRCON CONDENSER	Not Necessary	1,280.00 FL	*- FL
25	1		*RADIATOR ASSY	Not Necessary	1,138.00 FL	*- FL
26	1		*RADIATOR FAN ASSY	Not Necessary	848.00 FL	*- FL
27	1		*FRONT DOOR PANEL LH	Repair	1,401.00 FL	*- FL
28	1		*FRONT NUMBER PLATE	Not Necessary	100.00 FS	*- FS
29	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*FRONT FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
31	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*BOT COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,118.00	5,522.65
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,576.80	542.27
Total Parts (\$\$)	14,541.20	4,980.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT ELECTRICAL WIRING AND TEST FOR PROPER FUNCTIONING	New	150.00	20.00
2	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	New	150.00	0.00
3	TO REMOVE,REFIT AND TEST FOR PROPER FUNCTIONING-CONDENSER+TOP UP GAS	New	200.00	100.00
4	TO REMOVE,REFIT AND TEST FOR PROPER FUNCTIONING-RADIATOR+TOP UP COOLANT	New	200.00	0.00
5	TO REMOVE,REFIT AND TEST FOR PROPER FUNCTIONING-ABS PUMP	New	200.00	50.00
6	ALIGNMENT	New	100.00	60.00
7	TO TRANSFER DOOR COMPONENT FROM OLD TO NEW	New	200.00	0.00
8	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	90.00
9	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	1,400.00	950.00
10	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,900.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >