

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011999/AGA3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100409706
Claimant Vehicle No :	SMG9074L	Insured Vehicle No :	SCE8106P
Date of Loss:	23/11/2021	Nature of Claim:	TP
		Claim No:	0878948475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9074L	Engine No:	L15B5551918
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11301910
Reg. Date:	03/01/2019 (Man. Year: 2018)	Odometer:	56640 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,415.44	14,139.80	5,275.64	27.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,710.00	3,620.00	3,090.00	46.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,125.44	17,759.80	8,365.64	32.02
+ GST 7.00/7.00% (S\$)	1,828.78	1,243.19	585.59	32.02
Nett Amount (S\$)	27,954.22	19,002.99	8,951.23	32.02
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,604.99		
Global Sum Settlement (S\$)		20,400.00		

INSPECTION

Date of Assignment:	24/11/2021	
Date Inspected:	24/11/2021	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	14.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,203.60 FL	*1,100.00 FL
2	1		*REAR BOOT LID WEATHERSTRIP	Cut	171.70 FL	*171.70 FL
3	1		*REAR BOOT LID MECHANISM LOCK	Damaged	187.10 FL	*187.10 FL
4	2		*REAR BOOT HINGE L/R	Not Necessary	136.00 FL	*- FL
5	2		*REAR BOOT DAMPER L/R	Bent	421.40 FL	*421.40 FL
6	2		*REAR BOOT LAMP L/R	Cracked	756.20 FL	*756.20 FL
7	1		*REAR BOOT LID NO PLATE LAMP	Not Necessary	48.50 FL	*- FL
8	1		*REAR NO PLATE GARNISH WITH CHROME TRIM	Cracked	316.20 FL	*316.20 FL
9	1		*REAR BOOT LID HONDA LOGO	Necessary	58.60 FL	*58.60 FL
10	1		*REAR BOOT LID VEZEL EMBLEM	Necessary	98.00 FL	*98.00 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	161.85 FL	*161.85 FL
12	1		*REAR WIPER MOTOR ASSY	Not Necessary	238.00 FL	*- FL
13	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	234.60 FL	*234.60 FL
14	2		*REAR BOOT LID INNER TOP TRIM GARNISH L/R	Not Necessary	160.80 FL	*- FL
15	1		*REAR BOOT LID INNER HANDLE HOLDER	Not Necessary	30.05 FL	*- FL
16	1		*REAR FENDER RH	Repair	680.20 FL	*- FL
17	2		*REAR LAMP ASSY L/R	Cracked	1,256.60 FL	*990.00 FL
18	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	109.60 FL	*109.60 FL
19	1		*REAR LOWER BUMPER ASSY	Deformed	982.00 FL	*765.00 FL
20	8		*REAR LOWER BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
21	1		*REAR BUMPER REFLECTOR L/R	O/S Cracked	316.00 FL	*158.00 FL
22	1		*REAR END PANEL	Distorted	695.20 FL	*545.00 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Deformed	125.30 FL	*125.30 FL
24	1		*REAR TYRE PANEL	Distorted	820.30 FL	*820.30 FL
25	1		*REAR TYRE PANEL TRIM BOARD COVER	Deformed	321.80 FL	*295.00 FL
26	1		*REAR TOOLS SPONGE	Cracked	215.10 FL	*215.10 FL
27	2		*REAR FENDER INNER TRIM GARNISH L/RH	Cracked	1,096.00 FL	*790.40 FL
28	2		*REAR FENDER WHEEL ARC TRIM GARNISH L/R	Cracked	624.00 FL	*397.40 FL
29	1		*REAR TYRE PANEL UNDER SHIELD COVER	Deformed	181.50 FL	*181.50 FL
30	8		*REAR TYRE PANEL UNDER SHIELD COVER CLIPS	Necessary	30.40 FL	*30.40 FL
31	1		*REAR EXHAUST SILENCER BOX ASSY WITH BUSHING	Bent	852.20 FL	*685.00 FL
32	1		*REAR DOOR MECHANISM LOCK RH	Not Necessary	123.50 FL	*- FL
33	1		*REAR AXLE BEAM ASSY	Not Necessary	1,645.90 FL	*- FL
34	2		*REAR LAMP PANEL L/R	Repair	318.20 FL	*- FL
35	1		*FRT BUMPER	Distorted	798.00 FL	*798.00 FL
36	2		*FRT BUMPER SIDE HOLDER L/R	Necessary	70.00 FL	*70.00 FL
37	1		*FRT BUMPER REINFORCEMENT	Dented	598.00 FL	*395.00 FL
38	1		*FRT BUMPER LOWER AIR GRILLE	Cracked	186.50 FL	*186.50 FL
39	1		*FRT LOWER BUMPER EXTENSION	Torn	394.50 FL	*394.50 FL
40	1		*FRT GRILLE ASSY	Cracked	480.00 FL	*480.00 FL
41	1		*FRT GRILLE CHROME TRIM	Cracked	498.70 FL	*498.70 FL
42	1		*FRT GRILLE HONDA LOGO	Necessary	55.00 FL	*55.00 FL
43	2		*HEADLAMP ASSY L/R	Cracked	3,787.60 FL	*3,787.60 FL
44	2		*HEADLAMP BRACKET L/R	Cracked	137.00 FL	*137.00 FL
45	2		*FRT GRILLE BRACKET L/R	Cracked	76.00 FL	*76.00 FL
46	2		*REAR SHOCK ABSORBER L/R	Not Necessary	660.00 FL	*- FL
47	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Crumpled	91.30 FL	*91.30 FL
48	2		*REAR SIDE BUMPER L/R	Deformed	390.00 FL	*390.00 FL
49	1		*REAR BUMPER INNER SIDE SHIELD RH	Not Necessary	103.80 FL	*- FL
50	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
51	1		*SET REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
52	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
53	2		*SETS FRT & REAR NO PLATE W/FRAME	Damaged	90.00 FS	*90.00 FS
54	2		*REAR TYRE PANEL TRIM BOARD COVER LOCK L/R	Cracked	253.00 FL	*253.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	24,061.80	17,592.25
					- List Item Discount on L Items 20.00/20.00% (\$)	4,646.36	3,452.45
					Total Parts (\$)	19,415.44	14,139.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	150.00	60.00
2	TO REMOVE REPLACE REAR WINDSCREEN	New	200.00	120.00
3	TO REMOVE REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	300.00	80.00
4	TO REMOVE,REINSTAL REAR EXHAUST TO FACILITATE REPAIR	New	200.00	80.00
5	TO REMOVE ,REPLACE REAR UNDERCARRIAGE PARTS	New	380.00	0.00
6	TO REMOVE ,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	280.00	80.00
7	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	2,800.00	1,800.00
8	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	2,400.00	1,400.00
			Gross Labour Cost (\$)	6,710.00
				3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >