



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200471

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 21/01/2022
Reference CC4/FCI21012000/Vpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBB 656Z
Insured Veh. GBJ 9285J
Claim No. D21003274MFCV
Policy No. D21097582
Accident Date 23/11/2021
Inspection Date 26/11/2021

Description	Total
Survey Inspection	483.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	483.00
GST (7%)	33.81
Grand Total	516.81

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21012000/Vpa3q2	
			Date: 21/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 9285J	Veh. Inspected	GBB 656Z
	Policy No.	D21097582	Coverage (\$)	0.00
	Claim No.	D21003274MFCV	Excess (\$)	0.00
	Assign From	ESTHER	Assign Date	25/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JN1SC2F24Z0800273	Colour	SILVER
	Odometer	235657 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DUNLOP	5 mm
	L/H Front Tyre	195 R15C	DUNLOP	5 mm
	R/H Rear Tyre	165 R13	BRIDGESTONE	5 mm
	L/H Rear Tyre	165 R13	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/11/2021	Inspection Date	26/11/2021
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 656Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DEFORMED	1,605.56	1,399.00
1	TAILGATE LOWER MEMBER	DENTED	756.80	586.50
1	TAILGATE LOWER HINGE	DENTED	224.40	138.00
2	TAILGATE SIDE HINGE	N/S DENTED / O/S SERVICEABLE	149.60	74.80
2	TAILGATE SIDE LOCK	N/S DENTED / O/S SERVICEABLE	400.40	142.30
2	TAILGATE SIDE LOCK CATCH	N/S CUT / O/S SERVICEABLE	149.60	74.80
1	TAILGATE EMBLEM -NISSAN	NECESSARY	97.90	97.90
2	TAILGATE DAMPER	N/S DISTORTED / O/S SERVICEABLE	40.80	20.40
2	TAILLAMP	N/S CRACKED / O/S SERVICEABLE	585.86	292.78
2	TAILLAMP PANEL	N/S DENTED / O/S SERVICEABLE	183.80	84.20
1	C BRACKET	SERVICEABLE	292.60	-
1	SPARE TYRE LOCK SCREW	SERVICEABLE	25.90	-
1	SPARE TYRE TOP MEMBER	SERVICEABLE	378.40	-
1	TOW HOOK	DENTED	134.20	134.20
1	TOW HOOK BRACKET	SERVICEABLE	151.80	-
1	FRONT BUMPER	DEFORMED	1,270.50	768.02
1	FRONT BUMPER BRACKET	DENTED	96.90	96.90
1	FRONT GRILLE	DISTORTED	737.66	438.40
1	FRONT GRILLE EMBLEM -LOGO	NECESSARY	75.90	75.90
2	FRONT HEADLAMP	CRACKED	1,139.60	946.80
2	FRONT HEADLAMP UNDER COVER	N/S DENTED / O/S SERVICEABLE	178.20	89.10
1	FRONT PANEL	DEFORMED	1,747.90	1,412.70
1	FRONT PANEL EMBLEM	NECESSARY	70.40	70.40
1	FRONT WIPER PANEL	DEFORMED	578.05	340.00
1	FRONT WIPER LINK	CRACKED	151.80	151.80
1	FRONT CORNER PANEL LH	MISSING	479.93	200.00

Report Ref No. CC4/FCI21012000/Vpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WING MIRROR ASSY LH	SERVICEABLE	201.30	-
1	ROUND MIRROR ASSY LH	SERVICEABLE	315.70	-
	LESS 10% DISCOUNT		-1,222.15	-763.49
			10,999.31	6,871.41
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NECESSARY	80.00	40.00
1	FLOOR WOODEN BOARD (SN)	CUT	800.00	250.00
1	TAILGATE STICKER -70KM (SN)	NECESSARY	50.00	30.00
1	TAILGATE STICKER -13 PAX (SN)	NECESSARY	50.00	30.00
1	FRONT NUMBER PLATE (SN)	NECESSARY	80.00	40.00
1	FRONT GRILLE CLIP (SN)	NECESSARY	30.00	20.00
			1,090.00	410.00
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTING SYSTEM.		80.00	50.00
	REMOVE AND REPLACE TAILGATE FROM OLD TO NEW .		150.00	60.00
	REMOVE AND REPLACE REAR FLOOR WOODEN BOARD.		200.00	40.00
	PANEL BEATING ON AFFECTED AREAS.		1,500.00	1,000.00
	SPRAY PAINTING ON AFFECTED AREAS .		1,500.00	850.00
	APPLY ANTI-RUST ON AFFECTED AREAS .		150.00	40.00
			3,580.00	2,040.00
	GRAND TOTAL		15,669.31	9,321.41
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00

Report Ref No. CC4/FCI21012000/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 656Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 656Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBB 656Z

RE-INSPECTION

