LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21012001/VVF3E2

Date: 02/12/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MW009326

Claimant Vehicle Policy No: MW009326

No: SHC7350H Insured Vehicle No: SKW3525G

Date of Loss: 24/11/2021 Nature of Claim: TP Claim No: M2105446

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC7350H

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU080157

Reg. Date: 23/08/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU107261

Colour: Yellow Odometer: 515106 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm
West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,867.75	1,408.36	3,459.39	71.07
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		1,600.00	680.00	920.00	57.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross Tot	tal (S\$)	6,478.75	2,099.36	4,379.39	67.60
Approved Total (Overridde	n) (S\$)		1,700.00		
	(S\$)	6,478.75	1,700.00	4,778.75	73.76
+ GST 7.00/7.00)% (S\$)	453.51	119.00	334.51	73.76
Nett Amou	int (S\$)	6,932.26	1,819.00	5,113.26	73.76

INSPECTION

Date of Assignment: 25/11/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 26/11/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHC7350H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Par	ticulars	Condition	Repairer's	Reference	Amount
1	1	*RE	EAR BUMPER COVER	Cut	459.40 FL	-	*459.40 FI
2	1	*RE	EAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FI
3	1	*RE	EAR BUMPER CENTRE MOULDING ASSY	Scratched	451.25 FL	-	*451.25 FI
4	1	*RE	AR BUMPER REINFORCEMENT	Dented	394.80 FL	-	*394.80 FI
5	1	*RE	AR BUMPER REINFORCEMENT BRACKET LH	Serviceable	138.10 FL	-	*- FI
3	1	*RE	AR BUMPER REINFORCEMENT BRACKET RH	Serviceable	138.10 FL	-	*- FI
7	1	*RE	AR BUMPER TOWING COVER	Serviceable	98.80 FL	-	*- FI
3	1	*RE	EAR BUMPER REFLECTOR LAMP RH	Serviceable	41.45 FL	-	*- FI
9	1	*AN	ITENNA ASSY SMARTKEY	Serviceable	40.50 FL	-	*- FI
10	1	*RE	EAR BUMPER FOG LAMP	Serviceable	201.50 FL	-	*- FI
11	1	*RE	AR PANEL	Serviceable	532.00 FL	-	*- FI
12	1	*RE	EAR PANEL GARNISH	Serviceable	346.80 FL	-	*- FI
13	1	*BC	OOTLID	Repair	2,480.40 FL	-	*- FI
14	1	*BC	OOTLID HYUNDAI PLATE	Serviceable	24.30 FL	-	*- FI
15	1	*EN	MBLEM HYBRID	Serviceable	24.30 FL	-	*- FI
16	1	*EN	MBLEM - IONIQ	Serviceable	31.30 FL	-	*- FI
17	1	*BC	OOTLID ADVERTISEMENT LOGO	Not Necessary	100.00 FN	-	*- FI
18	1	*BC	OOTLID COMFORT TEL NO STICKER	Not Necessary	35.00 FN	-	*- FI
19	1	*BC	OOTLID COMFORT LOGO STICKER	Not Necessary	30.00 FN	-	*- FI
20	1	*BC	OOTLID COMFORT APP STICKER	Not Necessary	30.00 FN	-	*- FI
21	1	*RE	EAR BUMPER REVERSE SENSOR	Cut	180.00 FN	-	*180.00 FI
<u>Sup</u>	<u>pleme</u>	entary #1					
22	1	*RE	EAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 FS	-	*55.00 F
23 ==Fra	1 anchise		EAR BUMPER LOWER CTR MOULDING L=ListItemDisc. N=NettItemDisc.	Distorted	155.00 FL	-	*155.00 FI
				Sub Total (S\$)	6,010.00	1,717.45	
			- List Item Discount on L Items 20		1,116.00	296.49	
			- Nett Item Discount on N Items	7.00/7.00% (S\$)	26.25	12.60	
				Total Parts (S\$)	4,867.75		1,408.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cella	neous Items			
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	250.00
3	CHK ALL LIGHTING	New	60.00	30.00
4	TUFF KOTE	New	60.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	20.00
		Gross Labour Cost (S\$)	1,600.00	680.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >