

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	Ref:		CS3/LPC21012003/R1tf3e2		
	300 BEACH ROAD SINGAPORE 1995		Date:	03/12/2021		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GX 7804S	Veh. Inspected		SMG 8683K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	212121VC00025180	Excess (\$)		0.00	
	Assign From	KENNY LIM	Assign Date		26/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HARRIER	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTEKB3GH00J004054	Colour		BLACK	
	Odometer	47017 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/55 R18	YOKOHAMA		6 mm	
	L/H Front Tyre	235/55 R18	YOKOHAMA		6 mm	
	R/H Rear Tyre	235/55 R18	YOKOHAMA		6 mm	
	L/H Rear Tyre	235/55 R18	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information					
	Accident Date	22/11/2021	Inspect Date /	Time	30/11/2021 ( 04:10 PM )	
	Survey held at	neld at 833 MOTORSPORTS				
		BLK 20 SIN MING IND.EST.SECTOR A #01-16 SINGAPORE 575678				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21012003/R1tf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

**Automotive Assessor** 

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$ 

REGD Auto Consultant-SAE, Licensed Appraiser