



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TP EQ

Xiao Chen

LKK

DATE 02/12/2021 OUR REF UAPL1501 4927
REPAIR ESTIMATE TO THE HYUNDAI ACCENT NO: SMS5427X

REAR ITEM

1 REAR BOOT ASSY	Dented	\$ 1,333.90	x.
2 REAR BOOT HINGES	Not new	\$ 269.20	x.
1 REAR BOOT INNER TRIM BOARD	New	\$ 201.40	x.
1 REAR BOOT LOCK	Dented	\$ 166.80	x.
1 REAR BOOT LOCK STRIKER	New	\$ 25.60	x.
1 REAR BOOT WEATHERSTRIP	cut	\$ 99.50	x.
1 REAR BOOT OUTER CHROME STRIP	New	\$ 75.80	x.
1 REAR BOOT EMBLEM	New	\$ 25.00	x.
1 REAR BOOT (ACCENT) EMBLEM	New	\$ 35.00	x.
2 REAR TAILLAMP ASSY	cut	\$ 852.00	x.
2 REAR TAILLAMP SIDE CLIPS	New	\$ 40.80	x.
2 REAR TAILLAMP PANEL	Repair	\$ 395.20	x.
1 REAR TAIL END PANEL	Dented	\$ 649.00	x.
1 REAR TAIL END PANEL INNER GARNISH	Deformed	\$ 125.00	x.
1 REAR SMART KEYLESS SENSOR (INNER)	Cracked	\$ 113.60	x.
1 REAR SMART KEYLESS SENSOR (OUTER)	Cracked	\$ 112.60	x.
1 REAR BUMPER FACE	Distorted	\$ 643.00	x.
1 REAR BUMPER REINFORCEMENT	cracked	\$ 476.00	x.
2 REAR BUMPER REINFORCEMENT BRACKET (LOWER)	Dented	\$ 128.00	x.
4 REAR BUMPER REVERSE SENSOR	Dented	\$ 700.00	x.
2 REAR BUMPER SIDE RETAINERS	New	\$ 136.00	x.
1 REAR BUMPER CLIPS (1 SET)	New	\$ 50.00	x.
2 REAR BUMPER LOWER REFLECTOR	Not new	\$ 109.20	x.
1 REAR L/H FENDER ASSY	Repair	\$ 1,786.00	x.
1 REAR R/H FENDER ASSY	Cracked	\$ 1,786.00	x.
2 REAR FENDER INNER SIDE GARNISH	RH torn	\$ 455.00	x.
1 REAR WINDSCREEN MOULDING	New	\$ 152.00	x.
1 REAR SPARE TYRE TOP COVER	torn	\$ 265.00	x.
1 REAR FLOOR PANEL	Repair	\$ 869.00	x.
		\$ 12,164.40	
	LESS 20%.....	\$ 2,432.88	
		\$ 9,731.52	

SPECIAL NETT:-

1 REAR NUMBER PLATE	New	\$ 50.00	x.
1 REAR WINDSCREEN GLASS RUBBER GUM	New	\$ 60.00	x.

LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR	\$ 150.00	80
TO DISM/REWIRE DAMAGED PORTION	\$ 180.00	30
TO DISM/REFIX REAR WINDSCREEN GLASS IN REPAIR	\$ 160.00	120
TO DISM/REFIX ROOF LINING SEAT GARNISH IN REPAIR	\$ 220.00	80
TO DISM/RENEW REAR REVERSE SENSOR	\$ 100.00	50
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$ 1,800.00	1400
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 1,300.00	1100
	\$ 13,751.52	

Adrian L
H/S 25/11/21
09 Days.