

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012007/Dqy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 30/12/2021 SINGAPORE 068811 ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 5731E Veh. Inspected SJD 9976K Policy No. VFX/P2413997 Coverage (\$) 0.00 Claim No. S1M03MX9 Excess (\$) 0.00 **CHAN KIAN CHUAN Assign Date** 26/11/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA STREAM Make & Model 1799 C.C HIDDEN 2008 Engine No. Year of Reg. RN61062325 SILVER Chassis No. Colour Odometer 231972 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 WEST LAKE 5 mm L/H Front Tyre 205/55 R16 WEST LAKE 5 mm 205/55 R16 WEST LAKE R/H Rear Tyre 5 mm WEST LAKE L/H Rear Tyre 205/55 R16 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. 5. **General Information** 20/11/2021 13/12/2021 ( 04:30 PM ) Accident Date Inspect Date / Time JL AUTO SERVICES PTE LTD Survey held at BLK 3006 UBI ROAD 1 #01-346 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/ASM21012007/Dgy3e2

**Estimate Days of Repair** 

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$400-\$500

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**Inspected By** 

5b.

ANG BRYAN TANI

Tu

K.K.LAU CPT(RET)

Automotive Assessor / Investigator

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

2 Working Days