

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012015/AVY3N2**Date:** 04/03/2022**REFERENCE**

Insured/Claimant:	LIEW MUN KIONG	Policy No:	7210074983	
Date of Loss:	21/11/2021	Nature of Claim:	OD	Claim No: 5458746690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8218T		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC41672
Reg. Date:	28/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30M1128013
Colour:	Red	Odometer:	3631 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,956.00	3,566.32	9,389.68	72.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	3,172.00	4,300.00	57.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,428.00	6,738.32	13,689.68	67.01
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	20,028.00	6,338.32	13,689.68	68.35
+ GST 7.00/7.00% (\$\$)	1,401.96	443.68	958.28	68.35
Nett Amount (\$\$)	21,429.96	6,782.00	14,647.96	68.35

INSPECTION

Date of Assignment:	26/11/2021		
Date Inspected:	25/11/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Torn	1,335.00 FS	*1,068.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	59.00 FS	*- FS
4	1	*FRONT BUMPER TRIM-CENTER	Not Necessary	356.00 FS	*- FS
5	1	*FRONT BUMPER GRILLE-CENTER	Not Necessary	217.00 FS	*- FS
6	1	*FRONT PARKING AID SENSOR SUPPORT-LH	Not Necessary	25.00 FS	*- FS
7	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
8	1	*FRONT BUMPER SPOILER	Deformed	763.00 FS	*610.00 FS
9	1	*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
10	1	*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	153.00 FS	*- FS
11	1	*FRONT BUMPER TRIM-LH	Not Necessary	164.00 FS	*- FS
12	1	*FRONT PARKING AID SENSOR SUPPORT OUTER-LH	Not Necessary	25.00 FS	*- FS
13	1	*FRONT PARKING AID SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
14	1	*FRONT FENDER-LH	Dented	1,286.00 FS	*1,028.80 FS
15	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
16	1	*FRONT FENDER BRACE-LH	Not Necessary	88.00 FS	*- FS
17	1	*FRONT FENDER BRACKET-LH	Not Necessary	32.00 FS	*- FS
18	2	*FRONT WHEEL ARCH TRIM COVER-LH/RH	N/s Cut/O/s Necessary	1,072.00 FS	*857.60 FS
19	1	*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	39.00 FS	*- FS
20	1	*HEADLIGHT MOUNTING-LH	Not Necessary	118.00 FS	*- FS
21	1	*HEADLIGHT-LH	Not Necessary	5,589.00 FS	*- FS
22	1	*LIFT CYLINDER-LH	Not Necessary	210.00 FS	*- FS
23	1	*LIFT CYLINDER-HOSE	Not Necessary	80.00 FS	*- FS
24	1	*FRONT WHEEL HOUSING LINER-LH	Not Necessary	240.00 FS	*- FS
25	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
26	1	*FRONT WHEEL HOUSING LINER LOWER COVER	Not Necessary	16.00 FS	*- FS
27	1	*SUNDRIES	Necessary	300.00 FS	*1.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,956.00 3,566.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS OR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			7,472.00	3,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >