

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012016/AQY3N2**Date:** 04/03/2022REFERENCE

Insured/Claimant: GWEE SIONG MONG Policy No: 2100500708
Date of Loss: 22/11/2021 Nature of Claim: OD Claim No: 9627083466SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL1171C**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN024187
Reg. Date: 14/02/2017 (Man. Year: 2016) Chassis No: WAUZZZF42HA067956
Colour: Black Odometer: 86093 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,177.00	5,332.88	13,844.12	72.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,652.00	2,350.00	46.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,179.00	7,984.88	16,194.12	66.98
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,579.00	7,384.88	16,194.12	68.68
+ GST 7.00/7.00% (S\$)	1,650.53	516.94	1,133.59	68.68
Nett Amount (S\$)	25,229.53	7,901.82	17,327.71	68.68

INSPECTION

Date of Assignment: 26/11/2021
Date Inspected: 25/11/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS (Npa)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	210.00 FS	*- FS
6	2		*FRONT AIR GUIDE-LH/RH	Not Necessary	126.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Cracked	1,152.00 FS	*921.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	135.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	36.00 FS	*- FS
13	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	58.00 FS	*- FS
17	1		*HORN-LH	Not Necessary	126.00 FS	*- FS
18	1		*HORN BRACKET-LH	Not Necessary	29.00 FS	*- FS
19	2		*BONNET HINGE-LH/RH	Not Necessary	610.00 FS	*- FS
20	1		*BONNET IMPACT PROTECTION-CENTER/LH/RH (3 Pcs)	Necessary	84.00 FS	*65.68 FS
21	1		*BONNET STRIKER-LH	Not Necessary	50.00 FS	*- FS
22	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
23	2		*BONNET BOWDEN CABLE CENTER-INNER/OUTER	Not Necessary	116.00 FS	*- FS
24	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
25	1		*PLENUM CHAMBER	Not Necessary	97.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	240.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (Npa)	Not Necessary	0.00 FS	*- FS
28	1		*FRONT WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
29	1		*FRONT SPOILER-LH	Not Necessary	35.00 FS	*- FS
30	1		*HEADLIGHT-LH	Not Necessary	7,693.00 FS	*- FS
31	1		*LIFT CYLINDER	Not Necessary	210.00 FS	*- FS
32	1		*LIFT CYLINDER HOSE	Not Necessary	93.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE INNER-LH	Not Necessary	28.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE OUTER-LH	Not Necessary	12.00 FS	*- FS
35	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
36	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
38	1		*BONNET	Dented	3,246.00 FS	*2,596.80 FS
39	1		*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	16.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,177.00 5,332.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER,BONNET AND HINGES	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	5,002.00
				2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >