

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI21012018/UTF3E2

**Date:** 28/12/2021

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** FBL8814D

**Insured Vehicle No :** SKU1341T

Date of Loss: 16/11/2021

Nature of Claim: TP

Claim No: CDMPG21002267

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL8814D**

Make & Model: YAMAHA YBR125, 123cc (M)

Engine No: E3F5E043561

Reg. Date: 03/05/2017 (Man. Year: 2017)

Chassis No: LBPRI101000058567

Colour: Red

Odometer: 25633 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 3.00-18

Front Left Side: Timsun 7 mm

Rear Left Side: Timsun 7 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,241.00	416.80	824.20	66.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	465.00	235.00	230.00	49.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,706.00</b>	<b>651.80</b>	<b>1,054.20</b>	<b>61.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>500.00</b>		
<b>(S\$)</b>	1,706.00	500.00	1,206.00	70.69
<b>+ GST 7.00/7.00% (S\$)</b>	119.42	35.00	84.42	70.69
<b>Nett Amount (S\$)</b>	<b>1,825.42</b>	<b>535.00</b>	<b>1,290.42</b>	<b>70.69</b>

### INSPECTION

Date of Assignment: 26/11/2021

Date Inspected: 26/11/2021

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 28 Dec 2021)	
<b>Parts:</b>	N/A	YAMAHA YBR125 123cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL8814D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER METER	Cracked	23.00 F	*23.00 FL
2	1		*CRASH BAR	Dented	203.00 F	*203.00 FL
3	1		*EMBLEM (YAMAHA) LOGO	Not Necessary	14.00 F	*- FL
4	1		*HEADLAMP ASSY	Scratched	147.00 F	*147.00 FL
5	1		*HOLDER CABLE	Not Necessary	6.00 F	*- FL
6	1		*LAMP SIGNAL FRONT LH	Not Necessary	21.00 F	*- FL
7	1		*LAMP SIGNAL REAR LH	Not Necessary	16.00 F	*- FL
8	1		*LAMP SIGNAL REAR RH	Not Necessary	21.00 F	*- FL
9	1		*LEVER BRAKE (SCRATCHED)	Not Consistent With The Impact	19.00 F	*- FL
10	1		*LEVER CLUTCH	Not Necessary	19.00 F	*- FL
11	1		*MIRROR RH (CUT)	Not Consistent With The Impact	35.00 F	*- FL
12	1		*MUDGUARD FRONT (RED)	Cracked	49.00 F	*49.00 FL
13	1		*PIPE EXHAUST ASSY	Not Necessary	399.00 F	*- FL
14	1		*PROTECTOR EXHAUST (CUT)	Not Consistent With The Impact	77.00 F	*- FL
15	1		*PROTECTOR EXHAUST CAP (CUT)	Not Consistent With The Impact	49.00 F	*- FL
16	2		*RUBBER FOOTREST FRONT	Not Necessary	28.00 F	*- FL
17	1		*SET STEERING CONE	Not Necessary	66.00 F	*- FL
18	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	19.00 FS	*10.00 FS
19	1		*VISOR	Cracked	30.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,241.00</b>	<b>462.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	45.20

<b>Total Parts (\$\$)</b>	<b>1,241.00</b>	<b>416.80</b>
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	315.00	200.00
2	REPAIR ON FORK ALIGNMENT	New	95.00	0.00
3	TRANSPORT CHARGES	New	55.00	35.00
<b>Gross Labour Cost (\$)</b>			<b>465.00</b>	<b>235.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >