

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21012019/KPA3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700049034
<b>Claimant Vehicle No :</b>	SHD9065M	<b>Insured Vehicle No :</b>	SLR4335X
Date of Loss:	23/11/2021	Nature of Claim:	TP
		Claim No:	9286506151SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9065M</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B79931
Reg. Date:	12/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU103077294
Colour:	Metallic Pearl White/Red	Odometer:	149487 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R5	Rear Tyre Size:	195/65 R5
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,376.17	4,239.10	2,137.07	33.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,590.00	2,000.00	55.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,966.17</b>	<b>5,829.10</b>	<b>4,137.07</b>	<b>41.51</b>
<b>+ GST 7.00/7.00% (S\$)</b>	697.63	408.04	289.59	41.51
<b>Nett Amount (S\$)</b>	<b>10,663.80</b>	<b>6,237.14</b>	<b>4,426.66</b>	<b>41.51</b>
<b>+ Loss of Use (8.0 x S\$50.00/day) (S\$)</b>		400.00		
<b>+ Car Rental (8.0 x S\$96.30/day) (S\$)</b>		770.40		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>7,414.99</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,415.00</b>		

INSPECTION

Date of Assignment:	25/11/2021		
Date Inspected:	25/11/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, REAR BUMPER	Bent / Cracked	442.60 FL	*442.60 FL
2	1		*GUARD ,REAR BUMPER CENTER	Bent	576.30 FL	*576.30 FL
3	1		*COVER ,REAR BUMPER LOWER	Serviceable	15.40 FL	*- FL
4	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Mtg Cracked	123.70 FL	*123.70 FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
6	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	116.50 FL	*116.50 FL
7	1		*COVER ,FLOOR UNDER ,NO.1 (LH)	Serviceable	175.10 FL	*- FL
8	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
9	1		*LENS AND BODY ,REAR LAMP ,LH	Serviceable	502.00 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Cracked	443.30 FL	*443.30 FL
11	1		*COVER,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
12	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Bent	650.30 FL	*650.30 FL
13	1		*PANEL SUB-ASSY ,BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
14	1		*GARNISH SUB-ASSY ,BACK DOOR, OUTSIDE	Cracked	925.60 FL	*925.60 FL
15	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
16	1		*STAY ASSY ,BACK DOOR ,RH	Repair	242.50 FL	*- FL
17	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
18	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
19	1		*PARKING AID	Dented	700.00 FS	*200.00 FS
20	1		*REAR FLOOR COVER CLIP	Not Necessary	60.00 FS	*- FS
21	1		*REAR LOWER BUMPER CLIP	Not Necessary	65.00 FS	*50.00 FS
22	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
23	1		*BOOT STICKER TRANSCAB	Necessary	100.00 FS	*30.00 FS
24	1		*BOOT STICKER TEL.NO	Necessary	100.00 FS	*30.00 FS
25	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
26	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
27	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,979.90</b>	<b>5,428.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,603.73	1,189.70
<b>Total Parts (\$\$)</b>	<b>6,376.17</b>	<b>4,239.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	600.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	880.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,590.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >