



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1523B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	NOT NECESSARY	1,455.10	-
1	FRONT BUMPER SIDE RETAINER-L	NOT NECESSARY	102.10	-
1	FRONT HEADLAMPS-L	NOT NECESSARY	3,606.10	-
1	FRONT FENDER	BADLY DENTED	988.20	988.20
1	FRONT FENDER INNER SHIELD	TORN	295.30	295.30
1	FRONT FENDER BRACKET	NOT NECESSARY	65.00	-
1	FRONT FENDER INNER GARNISH	TWISTED	122.10	122.10
1	FRONT FENDER WHEEL HOUSE PANEL	TO REPAIR SEE LABOUR	961.10	-
1	FRONT SIDE MIRROR ASSY	DAMAGED	1,245.20	1,245.20
1	FRONT FENDER QUARTER GLASS	BROKEN	680.50	680.50
1	FRONT FENDER PILLAR	TO REPAIR SEE LABOUR	845.20	-
1	FRONT DOOR-L	TO REPAIR SEE LABOUR	1,966.20	-
1	FRONT FENDER QUARTER GLASS MOULDING	DISTORTED	146.50	146.50
	LESS 25% DISCOUNT		-3,119.65	-869.45
			9,358.95	2,608.35
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT FENDER GLASS SEALANT (SN)	NECESSARY	40.00	30.00
1	FRONT FENDER GLASS SOLAR FILM (SN)	NECESSARY	120.00	80.00
1	FRONT FENDER SOUND PROOF INSULATOR (SN)	NECESSARY	280.00	280.00
1	FRONT FENDER INNER PANEL SOUND PROOF INSULATOR (SN)	NOT NECESSARY	280.00	-
			720.00	390.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT FRONT QUARTER GLASS.		150.00	80.00
	TO REMOVE,REPLACE DAMAGED LAMP AND CHECK UP FRONT WIRING.		100.00	20.00
	TO RESPRAY UNDERCOATING.		100.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER WHEEL HOUSE PANEL,FRONT FENDER PILLAR AND FRONT DOOR-L.		800.00	400.00

Report Ref No. CS/LPC21012027/Utf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00
			2,150.00	1,030.00
GRAND TOTAL			12,228.95	4,028.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/LPC21012027/Uff3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.