12/1/21, 12:05 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS3/CTI21012029/VTY3N2 Our File No:

01/12/2021 Date:

Claim

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00184182000

TP

Claimant Vehicle

PC5054G

Insured

SMA4094T

No:

Vehicle No:

Date of Loss:

24/11/2021

Nature of Claim:

SNM21D206817/C03/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

PC5054G Reg No:

TOYOTA HIACE, 3.0 COMMUTER GL (A) Make & Model: Engine No: 1KD2650193 Reg. Date: 19/10/2016 (Man. Year: 2016) Chassis No: KDH2230029631 Colour: Black Odometer: 180290 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/11/2021

Garage 13 Pte Ltd (HQ)

Date Inspected: 26/11/2021 Inspected At: 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46

Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: DENISE TAY KWEE CHENG Thevan Thomas Karthikesavan Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/1/21, 12:05 PM Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

12/1/21, 12:05 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Dec 2021)

Parts: N/A TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC5054G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

12/1/21, 12:05 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >