

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012030/T1GA3Q2**Date:** 17/08/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800152116-01
Claimant Vehicle No :	SMD2404E	Insured Vehicle No :	SKU8789P
Date of Loss:	25/11/2021	Nature of Claim:	TP
		Claim No:	5903266332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2404E	Engine No:	HIDDEN
Make & Model:	BLUECAR BLUECAR, (A)	Chassis No:	VL4BCEB4RJT003275
Reg. Date:	08/08/2018 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,671.20	6,158.55	2,512.65	28.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,100.00	1,370.00	55.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,141.20	7,258.55	3,882.65	34.85
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	11,141.20	5,800.00	5,341.20	47.94
+ GST 7.00/7.00% (S\$)	779.88	406.00	373.88	47.94
Nett Amount (S\$)	11,921.08	6,206.00	5,715.08	47.94
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,453.45		

INSPECTION

Date of Assignment:	26/11/2021		
Date Inspected:	29/11/2021	Inspected At:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Deformed	2,073.00 F	*2,073.00 F
2	10	*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
3	1	*FRONT REINFORCEMENT (WCP)	Bent	340.00 F	*340.00 F
4	2	*FRONT REINFORCEMENT BRACKET (WCP)	Not Necessary	560.00 F	*- F
5	1	*FRONT BUMPER SPONGE WITH CLIPS (WCP)	Deformed	225.00 F	*225.00 F
6	1	*REAR BUMPER (WCP)	Deformed	1,950.00 F	*1,950.00 F
7	1	*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	275.00 F	*- F
8	1	*REAR BUMPER REINFORCEMENT BRACKET LH (WCP)	Not Necessary	60.00 F	*- F
9	1	*REAR BUMPER REINFORCEMENT BRACKET RH (WCP)	Not Necessary	60.00 F	*- F
10	1	*REAR BUMPER REFLECTOR RH (WCP)	Cracked	173.00 F	*173.00 F
11	1	*REAR BUMPER REFLECTOR LH (WCP)	Not Necessary	172.00 F	*- F
12	1	*REAR END PANEL (WCP)	Repair	655.00 F	*- F
13	1	*CHARGE AIR INLET (WCP)	Deformed	172.00 F	*172.00 F
14	1	*CHARGE AIR INLET GASKET (WCP)	Deformed	8.00 F	*8.00 F
15	2	*REAR AIR VENT (BOOT/TRUNK) (WCP)	Not Necessary	92.00 F	*- F
16	2	*REAR NUMBER PLATE LAMP (WCP)	N/S Bent / O/S Distorted	316.00 F	*316.00 F
17	1	*NUMBER PLATE WITH CASING	Bent	90.00 FS	*90.00 FS
				Sub Total (\$)	7,241.00 5,367.00
				+ Margin on L,N Items 20.00/15.00% (\$)	1,430.20 791.55
				Total Parts (\$)	8,671.20 6,158.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	800.00	300.00
2	TO PUTTY AND RESPRAY FRONT BUMPER ,BONNET AND AFFECTED AREAS	New	400.00	200.00
3	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS ,INCLUDING PANEL BEAT ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	600.00	300.00
4	TO PUTTY AND RESPRAY REAR BUMPER ,REAR END PANEL ,REAR FLOOR PANEL AND AFFECTED AREAS	New	400.00	200.00
5	TO APPLY TUFF COATING	New	120.00	0.00
6	TO CHECK WIRING AND UPDATE SYSTEM	New	150.00	100.00
Gross Labour Cost (\$\$)			2,470.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >