

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21012038/ETF3N2**Date:** 07/01/2022**REFERENCE**

Insured/Claimant: LOH WAI KIT (LUO WEIJIE) Policy No: 2070035429  
Date of Loss: 26/11/2021 Nature of Claim: OD Claim No: 2645774240SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMS8413K**  
Make & Model: CITROEN C5, 1.6 (A) Engine No: 10FKBA2585408  
Reg. Date: 17/03/2020 (Man. Year: 2019) Chassis No: VR7A45GFRKL095839  
Colour: Grey Odometer: 50478 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: S\$120,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 235/60R17 Rear Tyre Size: 235/60R17  
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm  
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,700.00	6,125.20	1,574.80	20.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,085.00	2,535.00	550.00	17.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,785.00</b>	<b>8,660.20</b>	<b>2,124.80</b>	<b>19.70</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	10,185.00	8,060.20	2,124.80	20.86
<b>+ GST 7.00/7.00% (S\$)</b>	712.95	564.21	148.74	20.86
<b>Nett Amount (S\$)</b>	<b>10,897.95</b>	<b>8,624.41</b>	<b>2,273.54</b>	<b>20.86</b>

**INSPECTION**

Date of Assignment: 29/11/2021  
Date Inspected: 29/11/2021 Inspected At: Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)  
209 PANDAN GARDENS  
Singapore 609339  
Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,502.00 FL	*1,502.00 FL
2	1		*FRT SKIRT-PANEL	Broken	829.00 FL	*829.00 FL
3	1		*FR BMPR GRILLE	Broken	993.00 FL	*993.00 FL
4	1		*BRACKET SET	Necessary	109.00 FL	*109.00 FL
5	1		*FINISHER BUMPER	Necessary	93.00 FL	*93.00 FL
6	1		*FR BMPR GRILLE CENT	Not Necessary	132.00 FL	*- FL
7	1		*FR BMPR GRILLE LAT	Broken	148.00 FL	*148.00 FL
8	1		*FINISHER BUMPER LAT	Cut	224.00 FL	*224.00 FL
9	1		*FINISHER BUMPER	Not Necessary	116.00 FL	*- FL
10	1		*FR BMPR GRILLE INF	Broken	231.00 FL	*231.00 FL
11	1		*BUMPER ABSORBER	Broken	156.00 FL	*156.00 FL
12	1		*REAR DUCT	Broken	167.00 FL	*167.00 FL
13	1		*BUMPER BRACKET	Broken	342.00 FL	*342.00 FL
14	1		*BUMPER ABSORBER	Dented	370.00 FL	*370.00 FL
15	1		*BUMPER ABSORBER	Dented	499.00 FL	*499.00 FL
16	1		*FIXING STUD	Necessary	36.00 FL	*36.00 FL
17	1		*FACE CROSSMEMBR SUP	Not Necessary	201.00 FL	*- FL
18	1		*FACE CROSSMEMBR INF ASS	Not Necessary	80.00 FL	*- FL
19	1		*AIR BULKHEAD RH	Not Necessary	138.00 FL	*- FL
20	1		*FRONT LIGHT RH	Not Necessary	770.00 FL	*- FL
21	1		*HDLIGHT SUPPORT RH COMPLEMENTA	Not Necessary	72.00 FL	*- FL
22	1		*LIGHT MOULDING RH AV	Not Necessary	90.00 FL	*- FL
23	1		*HEADLIGHT ASSY RH	Broken	691.00 FL	*691.00 FL
24	1		*LUG REPAIR KIR	Not Necessary	140.00 FL	*- FL
25	1		*SENSOR	Not Necessary	192.00 FL	*- FL
26	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
27	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
28	1		*DEFLECTOR Supplementary	Broken	349.00 FL	*349.00 FL
29	1		*FRONT WING LH ASS Supplementary	Dented	539.00 FL	*539.00 FL
30	1		*WDSCRN MOULDING LH Supplementary	Broken	291.00 FL	*291.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,600.00</b>	<b>7,639.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,900.00	1,513.80
<b>Total Parts (\$\$)</b>	<b>7,700.00</b>	<b>6,125.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER & AFFECTED AREA	New	1,000.00	500.00
2	PAINT WORK ON FRT BUMPER PANEL	New	380.00	380.00
3	TO APPLY SEALANT ON AFFECTED AREA	New	50.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	225.00	225.00
6	MOUNTED ONTO FLOOR PULLING Supplementary	New	500.00	500.00
7	REPLACE LH FRONT FENDER Supplementary	New	500.00	500.00
8	SPRAY PAINT LH FRONT FENDER Supplementary	New	380.00	380.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,085.00</b>	<b>2,535.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**