

CYCLE & CARRIAGE

ATG - OD CLAIM  
SURVEY: 29/11/21  
VKK - STEVE

VEHICLE NO : SMS 843K

MODEL : CIT/C5 AIRCROSS 1.6 PURETECH

WIP : 17184

Material	:	\$	<u>6,055.20</u>
Labour	:	\$	<u>2,605.00</u>
Sub-Total	:	\$	<u>8,660.20</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>8,060.20</u>
GST 7%	:	\$	<u>564.21</u>
Grand Total	:	\$	<u>8,624.41</u>
Finalise By/Date	:	<u>WKK ON 30/12/21</u>	

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk end)



**PRO-FORMA INVOICE**

Company Reg No. 200609327M  
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /Mr LOH WAI KIT (LUO WEIJIE) Reg No/Reg Date SMS8413K / 17/03/2020 Date In/Mileage 29/11/2021/ 50478 Chassis/Package VR7A45GFRKL095839 /# Engine No 10FKBA2585408 Make/Model CIT/C5 AIRCROSS 1.6 PURETECH 180 S&S EAT Colour/Trim MOF CUMULUS GREY/WH/ OXF CUIR CLAUDIA/TI



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	30/12/2021/ 13:00	BLK	884 / Lauro Songcuan	17184	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER & AFFECTED AREAS				500.00 ✓
E PNT98000 PAINT WORK ON FRONT BUMPER PANEL				380.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				225.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00 ✓
E PNT88000 MOUNTED ONTO FLOOR PULLING				500.00 X
E PNT88000 REPLACE LH FRONT FENDER				500.00 X
E PNT98000 SPRAY PAINT LH FRONT FENDER				380.00 X
X EXC INSURANCE EXCESS				-600.00
M SUNDRY REAR DUCT ? PART NO: C9833398380			167.00 20%	133.60 ?
X FRONT BUMPER ✓	1.00	1502.00	20.00	1201.60 ✓
X FRT SKIRT-PANEL ✓	1.00	829.00	20.00	663.20 ✓
X BRACKET SET ?	1.00	109.00	20.00	87.20 ?
X FINISHER BUMPER ?	1.00	93.00	20.00	74.40 ?
X FR BMPR GRILLE LAT ?	1.00	148.00	20.00	118.40 ?
X FINISHER BUMPER LAT ✓	1.00	224.00	20.00	179.20 ✓
X FR BMPR GRILLE INF ?	1.00	231.00	20.00	184.80 ?
X BUMPER ABSORBER ?	1.00	156.00	20.00	124.80 ?
X BUMPER BRACKET ?	1.00	342.00	20.00	273.60 ?
X BUMPER ABSORBER ?	1.00	370.00	20.00	296.00 ?

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.  
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



**PRO-FORMA INVOICE**

Company Reg No. 200609327M  
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /Mr LOH WAI KIT (LUO WEIJIE) Reg No/Reg Date SMS8413K / 17/03/2020 Date In/Mileage 29/11/2021/ 50478 Chassis/Package VR7A45GFRKL095839 /# Engine No 10FKBA2585408 Make/Model CIT/C5 AIRCROSS 1.6 PURETECH 180 S&S EAT Colour/Trim MOF CUMULUS GREY/WH/ OXF CUIR CLAUDIA/TI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	30/12/2021/ 13:00	BLK	884 / Lauro Songcuan	17184	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BUMPER ABSORBER ?	1.00	499.00	20.00	399.20 ?
X FIXING STUD ✓	1.00	36.00	20.00	28.80 ✓
X HEADLIGHT ASSY RH ?	1.00	691.00	20.00	552.80 ?
X DEFLECTOR	1.00	349.00	20.00	279.20 x
X FRONT WING LH ASS } <i>Supp</i>	1.00	539.00	20.00	431.20 x
X WDSCRN MOULDING LH	1.00	291.00	20.00	232.80 x
X FR BMPR GRILLE ?	1.00	993.00	20.00	794.40 ?

Z TEXT  
 AIG - OD CLAIM  
 DOA: 26/11/2021  
 SURVEY: STEVE (LKK)  
 ↻ DAYS

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts		Nett	8,060.20
Labour		7% GST on	564.21
Standard Menu			
Specialist Job		Total Payable	8,624.41
Diagnostics Job		Paid	0.00
Sundry/Others		Total Due	8,624.41
Total(w/o GST)	8,060.20		

*Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.  
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.*



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMS 8413 K

<u>Materials</u>		<u>Cost (\$)</u>
1	Deflector - BR	349.00
2	Front Wing LH Ass - DD	539.00
3	Wdscrn Moulding LH - BR	291.00
		<u>1,179.00</u>
20% Discount		<u>235.80</u>
		<u>943.20</u>
<u>Labour</u>		
1	Mounted Onto Floor Pulling	500.00 -
2	Replace LH Front Fender	500.00 -
3	Spray Paint LH Front Fender	380.00 -
		<u>1,380.00</u>
Labour & Materials		2,323.20
7% GST		162.62
<b>Total</b>		<u><b>2,485.82</b></u>

Thank You.

Yours faithfully  
CYCLE & CARRIAGE FRANCE PTE LTD

LARRY SONGCUAN  
CUSTOMER SERVICE  
TEL: 6568 4658  
FAX : 6567 5258

CAR NO: SM 5 8413L

WIP: 17184

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	FR BMR grille (End grille)	? / SUPP		- RR	
2	Racket Set	? / SUPP		- RR	
3	Finisher Bumper	? / SUPP		- RR	
4	Finisher Bumper Lat	? / SUPP			
5	FR BMR grille Inf (Centre lower grille)	? / SUPP		- RR	
6	Bumper Absorber (Foam)	? / SUPP		- RR	
7	Rear Duct (Interchange de Parts)	? / SUPP		- RR	
8	Bumper Bracket (Top guard)	? / SUPP		- RR	
9	Bumper Absorber (Lower Reinforced)	? / SUPP		- RR	
10	Bumper Absorber (Upper " )	? / SUPP		- RR	
11	Headlight Assy RH	? / SUPP		- RR	
12	Deflector (under cover Bumper)	? / SUPP		- RR	
13	Front wing Left	? / SUPP		- RR	
14	Windscreen Moulding Left	? / SUPP		- RR	
15	Reinforce RH LH Fender	? / SUPP		- RR	
16	Mount on floor Pulling	? / SUPP		- RR	
17	Painting FR LH Fender	? / SUPP		- RR	
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	6/12/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: 05 AIRCROSS

SURVEYOR: Steve - Wk

Steve  
30/11/21



**Global test**

Expert/Global test  
Vehicle\menu\_tgref.s : 81\_02

FAMILY NO.		CONTROL UNIT
12		Built-in systems interface BSI2010_EV (12 Faults)

**U1F3E 87**      **Fault: no communication with telematic ECU**

**Properties**

Cause	Local
Status	Intermittent
Features	-

**B1808 87**      **Fault in the unlocking of the immobiliser by the engine management ECU**

**Properties**

Cause	Local
Status	Intermittent
Features	Request missing

**B116E 15**      **Left-hand direction indicator repeater control fault**

**Properties**

Cause	Local
Status	Intermittent
Features	Open circuit or short circuit to positive

Cause	Local
Status	Present
Features	Short circuit to positive

**B133D 13 Front window relay control output fault**

**Properties**

Cause	Local
Status	Present
Features	Open circuit

**B1727 13 Front left door handle circuit (keyless access and starting function)**

**Properties**

Cause	Local
Status	Intermittent
Features	Open circuit

**B120A 68 Collision risk alert function fault**


**Properties**

Cause	Local
Status	Present
Features	Detection of an impact

**B1418 00 Fault in the status of the seat belt fastening information for determining the presence of the driver**


**Properties**

Ancillaries battery charge status	89	%
Status of the ECU	Unlocked status	
Engine management ECU internal temperature	49	°C
Fuel high pressure common injection rail pressure	201	Bar
Synchronisation between the camshaft and the crankshaft	Synchronisation	



**Urea ECU**

**Communication error**



**Automatic or piloted manual gearbox**

★ **ECU not recognised**

*Down-grade mode: this information is not guaranteed*




**Sequential gear lever**

**ESM**




**Sequential gear lever**

**Communication error**



**Power steering**

**DAE\_BVH2**




**Anti-lock Braking System (ABS) or Electronic Stability Program (ESP)**

**ESP90**



**Battery charge status control unit** BECB\_GEN2



**Instrument panel**

**CIROCCO**



**Controls under the steering wheel**

★ **ECU not recognised**

*Down-grade mode: this information is not guaranteed*

Reg No: SMS8413K  
 After using DIAGBOX to  
 erase all the fault codes Job Done




## Global test

Expert/Global test

Vehicle\menu\_tgref.s : 81\_02

## FAMILY NO.

## CONTROL UNIT




Built-in systems interface

BSI2010\_EV




Engine management ECU

CMM\_MG1CS042



Urea ECU

Communication error


Automatic or piloted manual  
gearbox

★ ECU not recognised

Down-grade mode: this information is  
not guaranteed


Sequential gear lever

ESM



Sequential gear lever

Communication error



Power steering

DAE\_BVH2


Anti-lock Braking System (ABS)  
or Electronic Stability Program  
(ESP)

ESP90



Battery charge status control unit

BECB\_GEN2



Instrument panel

CIROCCO



Controls under the steering wheel

★ ECU not recognised

Down-grade mode: this information is  
not guaranteed




**Additional heating**

**Communication error**



**Electric steering lock**

**AVE**




**Diesel additive pump**

**Not present**




**Electric machine management ECU**

**Not present**




**Electrical brake servo master cylinder**

**Not present**




**Traction battery ECU**

**Not present**




**On-board charger / direct voltage transformer assembly**

**Not present**




**Electric/hybrid drive train supervisor ECU**

**Not present**



**Ancillaries battery 1 switch**

**Not present**



**Ancillaries battery 2 switch**

**Not present**




**Voltage maintaining device**

**Not present**




**Dynamic headlamp height adjuster**

**Not present**



**Pedestrian horn**

**Not present**



**Trailer relay unit**

**Not present**



**Traction control mode selector**

**Not present**