

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21012043/R1QF3E2

**Date:** 07/12/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070015069		
<b>Claimant Vehicle No :</b>	JTT7157	<b>Insured Vehicle No :</b>	SMS1685M		
Date of Loss:	18/11/2021	Nature of Claim:	TP	Claim No:	3904244747SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JTT7157	Engine No:	KF29E8059204
Make & Model:	HONDA VARIO, 149cc	Chassis No:	PMKKF3770KB012353
Reg. Date:	30/11/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	90/90-14	Rear Tyre Size:	100/90-14
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	29/11/2021	Inspected At: Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21 Singapore 568047
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: RM6,500.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
2	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cracked	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
5	2		*FRONT WING MIRROR	Scratched	0.00 F	*- F
6	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
7	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
8	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
9	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
10	2		*SIDE FAIRING	Cracked	0.00 F	*- F
11	1		*SIDE FAIRING INNER GARNISH	Scratched	0.00 F	*- F
12	2		*REAR FAIRING	Scratched	0.00 F	*- F
13	1		*FRT INNER CENTRE GARNISH	Cracked	0.00 F	*- F
14	1		*MAIN STAND	Scratched	0.00 F	*- F
15	2		*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
16	1		*REAR FOOT REST LH	Scratched	0.00 F	*- F
17	1		*REAR FENDER WHEEL GUARD	Cut	0.00 F	*- F
18	1		*REAR LH SIGNAL LAMP	Distorted	0.00 F	*- F
19	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>0.00 0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >