

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012048/AGA3Q2**Date:** 02/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700084881
<b>Claimant Vehicle No :</b>	SKW9093X	<b>Insured Vehicle No :</b>	SBA9933U
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	4516290337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKW9093X</b>	Engine No:	2ARF487218
Make & Model:	LEXUS ES250, 2.5 (A)	Chassis No:	JTHBJ1GG102105275
Reg. Date:	30/10/2017 (Man. Year: 2017)	Odometer:	88083 km
Colour:	Bronze		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,410.21	852.00	1,558.21	64.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	480.00	1,170.00	70.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,060.21</b>	<b>1,332.00</b>	<b>2,728.21</b>	<b>67.19</b>
<b>+ GST 7.00/7.00% (S\$)</b>	284.21	93.24	190.97	67.19
<b>Nett Amount (S\$)</b>	<b>4,344.42</b>	<b>1,425.24</b>	<b>2,919.18</b>	<b>67.19</b>
<b>+ Car Rental (3.0 x S\$180.00/day + 7.00% GST) (S\$)</b>		577.80		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,010.49</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,000.00</b>		

INSPECTION

Date of Assignment:	29/11/2021	SK Automobile Pte Ltd (HQ)
Date Inspected:	28/12/2021 Inspected At:	23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
Estimated Period of Repair:	2.0 days	Singapore 415933

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,035.00 FL	*- FL
2	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	145.00 FL	*- FL
3	1		*FRONT BUMPER LOWER CENTER GRILLE WITH CHROME MOLDING	Cut	880.00 FL	*880.00 FL
4	1		*FRONT BUMPER PARKING HOLDER (STICK ON)	Not Necessary	41.40 FL	*- FL
5	1		*FRONT BUMPER TOP RUBBER SEAL (STICK ON)	Not Necessary	93.50 FL	*- FL
6	1		*FRONT BUMPER INNER SPONGE	Not Necessary	122.00 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
8	1		*SET FRONT BUMPER NUMBER PLATE WITH CASING	Dented	85.00 FS	*60.00 FS
9	1		*SET FRONT BUMPER LOWER UNDER COVER CLIPS	Not Necessary	80.00 FS	*- FS
10	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (S\$)</b>	<b>2,641.90 940.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>231.69 88.00</b>
					<b>Total Parts (S\$)</b>	<b>2,410.21 852.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	500.00	200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	500.00	200.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	120.00	50.00
5	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,650.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >