



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9632L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	CUT / DEFORMED	1,079.00	493.30
2	FRONT BUMPER SIDE RETAINER @\$42.20 (N)	NOT NECESSARY	84.40	-
1	FRONT BUMPER LOGO (N)	NOT NECESSARY	79.60	-
1	FRONT BUMPER GRILLE WITH CHROME RIM (N)	CRACKED	315.10	276.70
1	FRONT BUMPER SPONGE (N)	NOT NECESSARY	198.30	-
1	FRONT BUMPER REINFORCEMENT (N)	NOT NECESSARY	409.90	-
2	FRONT BUMPER SPOT LIGHT @\$390.80 (N)	NOT NECESSARY	781.60	-
2	FRONT HEADLAMP @\$1695.30 (N)	NOT NECESSARY	3,390.60	-
1	SET FRONT BUMPER CLIP (N)	NECESSARY	67.00	35.00
	LESS 10% DISCOUNT		-640.55	-80.50
			5,764.95	724.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE WITH HOLDER (SN)	BENT	50.00	40.00
			50.00	40.00
<u>LABOUR</u>				
	PANEL BEATING.		700.00	200.00
	TO RESPRAY PAINTING ON AFFECTED AREAS.		700.00	200.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	100.00	-
	TO CHECK FRONT ELECTRICAL WIRING.		100.00	25.00
			1,600.00	425.00
GRAND TOTAL			7,414.95	1,189.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CS/SMO21012049/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.