

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012050/VEA3Q2**Date:** 17/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900079142-02
Claimant Vehicle No :	SHD3512D	Insured Vehicle No :	SKZ8066R
Date of Loss:	26/11/2021	Nature of Claim:	TP
		Claim No:	3607745673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3512D		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDGU672444
Reg. Date:	08/09/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU093486
Colour:	Blue	Odometer:	707250 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,229.72	2,134.20	4,095.52	65.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	550.00	410.00	42.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,189.72	2,684.20	4,505.52	62.67
Approved Total (Overridden) (\$\$)		2,150.00		
(\$\$)	7,189.72	2,150.00	5,039.72	70.10
+ GST 7.00/7.00% (\$\$)	503.28	150.50	352.78	70.10
Nett Amount (\$\$)	7,693.00	2,300.50	5,392.50	70.10
+ Loss of Use (4.5 x S\$50.00/day) (\$\$)		225.00		
+ Car Rental (4.5 x S\$110.67/day) (\$\$)		498.02		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,025.52		
Global Sum Settlement (\$\$)		3,020.00		

INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	29/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cut	1,052.20 FL	*1,052.20 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER BRACKET TOP LH	Necessary	44.80 FL	*44.80 FL
4	1		*RADIATOR GRILLE	Cut	1,480.00 FL	*1,480.00 FL
5	1		*HEADLAMP LH	Serviceable	1,388.00 FL	*- FL
6	1		*HEADLAMP SUPPORT PANEL	Serviceable	907.40 FL	*- FL
7	1		*FRT BUMPER GRILEL TOP GARNISH	Repair	80.00 FL	*- FL
8	1		*FRT BUMPER SPONGE	Serviceable	379.20 FL	*- FL
9	1		*FRT BUMPER REINFORCEMENT	Serviceable	588.40 FL	*- FL
10	1		*RADIATOR	Serviceable	1,637.20 FL	*- FL
11	1		*FRT BUMPER GRILLE AIR DUCT LH	Serviceable	126.20 FL	*- FL
12	1		*RADIATOR BRACKET LH	Serviceable	13.00 FL	*- FL
13	1		*FRT NUMBER PLATE WITH TRIM COVER	Scratched	55.00 FS	*55.00 FS
					Sub Total (\$\$)	7,773.40 2,654.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,543.68 519.80
					Total Parts (\$\$)	6,229.72 2,134.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHK ALL LIGHTING	New	60.00	20.00
Gross Labour Cost (\$\$)			960.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >