

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref: CS/SMR21012057/Auf3e2		
60 WOODLANDS INDUSTRIAL PARK E4		Date: 21/12/2021		
SINGAPORE 757705		Code: SMR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4860Y	Veh. Inspected	SMV 6409X	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/21/2053	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	29/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS NX300	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTJBABZ905020723	Colour	GREY	
Odometer	28704 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2021	Inspection Date	29/11/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		