

TP MS16

Denise.

STC3988X - 2012 March

BMW118i 1598cc

WBAIA320X2J064960

Rear Number Plate	cracked	30(SN) ✓
Rear Number Plate Holder	Deformed	30(SN) ✓
Rear Number Plate Lamp x02	And	26x2=52 ✓
Rear Camera.	Damaged	650(SN) 380(SN)
Rear Bumper	Deformed	1261 ✓
Rear Bumper Clips.	new	50(SN) ✓
Rear Bumper Side Holder x02	^{x4} new	88x2=176. x.
Rear Bumper Lower Garnish.	Cut	395 ✓
Rear Bumper Reinforcement.	Dented	449. ✓
Rear Bumper Centre Guide.	cracked	185 ✓
Reverse Sensor x04	2 piles damaged	250x4=1000 500
Reverse Sensor Holders.	new	28x4=112 ✓
Rear End Panel	x06 new	697 x
Rear End Panel Top Garnish.	^{x06} new	145. x.

8JC3888X

Rear End Panel Top Garnish clips } x4 20(SN) +
Rear End Panel Sealant } 1x 60(SN) +

Tail Lamp x02 Not 422XL = 844 +
new

Tailgate Dented 1230 ✓

Tailgate Lock Damaged 158 ✓

Tailgate Weatherstripe New 168 +

Tailgate Inner Trim Board Cracked 398 ✓
new

Tailgate Inner Trim Board clips 30(SN) ✓

Tailgate Glass Moulding } 145 ✓

Tailgate Glass Sealant } New 60(SN) ✓

BMW Logo } 80. ✓

Rear Exhaust Pipe Not 843 X.
New

4965 S.N: 580

4468.50

SJC3888X

Panel Beating

Spry Painting

Wiring.

To remove reuse sensor

To remove upholstery.

To transfer tailgate fittings.

To remove tailgate g/s

To remove rear camera.

1380

~~1200~~ 500

~~1200~~ 500

~~50~~ 30

~~100~~ 60

~~150~~ 40.

~~150~~ 80

~~180~~ 120

1000. 50.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 6428.50.

h/s: A.S.K (Nett Value)

04 Days.

4.5K