

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012060/EQF3E2

Date: 08/02/2022

REFERENCE

Insured/Claimant:	SHAHARUM BIN SULIAMAN	Policy No:	1700006332	
Date of Loss:	28/11/2021	Nature of Claim:	OD	Claim No: 3311430773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN46C	Engine No:	4B12SA1267
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	JMYXTGF3WHZ000704
Reg. Date:	18/05/2017 (Man. Year: 2016)	Odometer:	77926 km
Colour:	White		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,777.75	6,589.64	1,188.11	15.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,610.00	4,565.00	2,045.00	30.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,387.75	11,154.64	3,233.11	22.47
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,087.75	10,854.64	3,233.11	22.95
+ GST 7.00/7.00% (S\$)	986.14	759.82	226.32	22.95
Nett Amount (S\$)	15,073.89	11,614.46	3,459.43	22.95

INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	29/11/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*SET BODY KIT (NPA)	Broken	0.00 FS	*- FS
3	1		*FACE, FR BUMPER	Broken	810.00 FL	*810.00 FL
4	1		*COVER, FR BUMPER	Broken	281.00 FL	*281.00 FL
5	1		*EXTENSION, FR BUMPER	Cut	428.00 FL	*428.00 FL
6	1		*GARNISH, FR BUMPER, LH	Missing	78.00 FL	*78.00 FL
7	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 FL	*18.00 FL
8	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 FL	*- FL
9	1		*GARNISH, FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
10	1		*GARNISH, FR BUMPER SIDE	Missing	220.00 FL	*220.00 FL
11	1		*GARNISH, FR BUMPER SIDE	Missing	112.00 FL	*112.00 FL
12	1		*REINFORCEMENT, FR BUMPER	Dented	505.00 FL	*505.00 FL
13	1		*REINFORCEMENT, FR BUMPER	Not Necessary	135.00 FL	*- FL
14	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 FL	*60.00 FL
15	1		*REINF, FR BUMPER SIDE, RH	Not Necessary	69.00 FL	*- FL
16	2		*REINFORCEMENT, FR BMPR SIDE	Not Necessary	44.00 FL	*- FL
17	1		*HEADLAMP ASSY, LH	Broken	2,135.00 FL	*2,135.00 FL
18	1		*LAMP ASSY, FOG, FR	Not Necessary	224.00 FL	*- FL
19	1		*GRILLE ASSY, RADIATOR	Broken	572.00 FL	*572.00 FL
20	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
21	1		*COVER, FR BUMPER	Not Necessary	25.00 FL	*- FL
22	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 FL	*- FL
23	1		*BRACKET, RADIATOR GRILLE	Not Necessary	10.00 FL	*- FL
24	1		*HOOD	Dented	980.00 FL	*980.00 FL
25	1		*HINGE, HOOD, LH	Not Necessary	68.00 FL	*- FL
26	1		*HINGE, HOOD, RH	Not Necessary	68.00 FL	*- FL
27	9		*CLIP, HOOD INSULATOR	Not Necessary	27.00 FL	*- FL
28	1		*WEATHERSTRIP, HOOD	Not Necessary	41.00 FL	*- FL
29	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 FL	*- FL
30	4		*TAPE, TAILGATE	Not Necessary	16.00 FL	*- FL
31	1		*LATCH, HOOD	Not Necessary	76.00 FL	*- FL
32	1		*FENDER, FR LH	Dented	622.00 FL	*622.00 FL
33	1		*INSULATOR, FR FENDER, LH	Crushed	65.00 FL	*65.00 FL
34	1		*SHIELD, FR WHEELHOUSE, LH	Broken	164.00 FL	*164.00 FL
35	10		*CLIP, ENG ROOM COVER	Necessary	20.00 FL	*20.00 FL
36	1		*MOULDING, FR BUMPER, LH	Cut	116.00 FL	*116.00 FL
37	1		*MOULDING, FR BUMPER, RH	Not Necessary	116.00 FL	*- FL
38	1		*MOULDING, FR WHEEL ARCH, LH	Necessary	199.00 FL	*199.00 FL
39	1		*MOULDING, FR WHEEL ARCH, RH	Not Necessary	199.00 FL	*- FL
40	1		*HOSE ASSY, HEADLAMP WASHER	Torn	135.00 FL	*135.00 FL
41	1		*ACTUATOR, HEADLAMP WASHER, L	Broken	212.00 FL	*212.00 FL
42	1		*COVER, HEADLAMP WASHER HOLE	Missing	53.00 FL	*53.00 FL
43	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	230.00 FL	*- FL
44	1		*PNL, HEADLAMP SUPT, UPR LH	Bent	58.00 FL	*58.00 FL
45	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
46	1		*HARNESS, FOG LAMP (Supplementary)	Torn	130.00 FL	*130.00 FL
47	1		*COVER, ENG ROOM UNDER, FR (Supplementary)	Broken	349.00 FL	*349.00 FL
48	6		*RIVET, FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL
49	10		*CLIP, FR BUMPER (Supplementary)	Necessary	40.00 FL	*40.00 FL
50	20		*CLIP, RR BUMPER (Supplementary)	Necessary	60.00 FL	*60.00 FL
51	1		*HORN (Supplementary)	Bent	80.00 FL	*80.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					10,095.00	8,552.00
- List Item Discount on L Items 23.00/23.00% (\$)					2,317.25	1,962.36
Total Parts (\$)					7,777.75	6,589.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, LHF FENDER & FRT SUPPORT. REPAIR RHF FENDER & LHF DOOR	New	2,250.00	1,125.00
2	RESPRAY FR BUMPER, BONNET, FR SUPPORT, LHF FENDER, RHF FENDER & LHF DOOR	New	2,100.00	1,400.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AC GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	SUPPLY FR NUMBER PLATE WITH CASING	New	50.00	50.00
8	RESEAL FR WEEKEND NUMBER PLATE	New	120.00	100.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
10	SUPPLY BODY PNL SEALANT	New	60.00	40.00
11	APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS	New	160.00	160.00
12	REPLACE LH HEAD LAMP SUPPORT PANEL, FRONT REINFORCEMENT, LH TOP PANEL & WHEEL HOUSING (Supplementary)	New	450.00	450.00
13	SPRAY PAINT RH FRONT FENDER, LH A PILLAR, LH HEAD LAMP SUPPORT AND FRONT REINFORCEMENT (Supplementary)	New	1,050.00	1,050.00
Gross Labour Cost (S\$)			6,610.00	4,565.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >