

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------|---|--|----------------|------------|-------------------------|--|
| | AXA INSURANCE | PTE LTD | | Ref: | CS3/ASM21012068/Gqy3e2 | |
| | 8 SHENTON WAY SINGAPORE 0688 | | Date: | 03/12/2021 | | |
| | ATTN: ANG YVON | NE | | Code: | ASM | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SHB 4203A | Veh. Inspected | l | FBR 6396A | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | | 0.00 | |
| | Claim No. | S1M03LZH | Excess (\$) | | 0.00 | |
| | Assign From | ANG YVONNE | Assign Date | | 29/11/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | PIAGGIO VESPA PRIMAVERA 150 | c.c | | 155 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2020 | |
| | Chassis No. | RP8M82414KV000190 | Colour | | BLACK | |
| | Odometer | 28744 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 120/70-12 | PIRELLI | | 6 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 130/70-12 | MITAS | | 6 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND FRONT PORTION. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 10/11/2021 | Inspect Date / | Time | 30/11/2021 (03:00 PM) | |
| | Survey held at WASTE GARAGE SCOOTERS 8 KAKI BUKIT AVENUE 4, #03-02, PREMIER @ KAKI BUKIT, SINGAPORE 415875 | | | | | |
| | | | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |
| | Papert Ref No. CS2/ASM24042069/Cm/2e2 | | | | | |

Report Ref No. CS3/ASM21012068/Gqy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.