

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012069/KPA3Q2**Date:** 28/03/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070114859   |
| <b>Claimant Vehicle No :</b> | SJM8545E                             | <b>Insured Vehicle No :</b> | SMD7074R     |
| Date of Loss:                | 26/11/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 8766218170SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJM8545E</b>                   | Engine No:  | HIDDEN            |
| Make & Model:               | TOYOTA VIOS, 1.5 E (A)            | Chassis No: | MR053HY9305097397 |
| Reg. Date:                  | 01/01/2009 (Man. Year: 2009)      | Odometer:   | 223483 km         |
| Colour:                     | Metallic Gold                     |             |                   |
| Engine Capacity:            | 1497 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 185/65 R15       | Rear Tyre Size:  | 185/65 R15       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 1,582.74          | 1,582.74          | 0.00              | 0.00          |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 2,600.00          | 1,500.00          | 1,100.00          | 42.31         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>             | <b>4,182.74</b>   | <b>3,082.74</b>   | <b>1,100.00</b>   | <b>26.30</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>        |                   | <b>2,450.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                        | <b>4,182.74</b>   | <b>2,450.00</b>   | <b>1,732.74</b>   | <b>41.43</b>  |
| <b>+ Loss of Use (5.0 x S\$60.00/day) (\$\$)</b> |                   | 300.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>2,757.45</b>   |                   |               |

INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 29/11/2021               | Caris Autoworks Pte Ltd - SIN MING (HQ)  |
| Date Inspected:             | 30/11/2021 Inspected At: | 160 SIN MING DR #05-03 SIN MING AUTOCITY |
| Estimated Period of Repair: | 5.0 days                 | Singapore 575722                         |

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition | Repairer's | Amount     |
|-----|-----|----------|-------------------------------|-----------|------------|------------|
| 1   | 1   |          | *BUMPER (REAR)                | Bent      | 457.50 FL  | *457.50 FL |
| 2   | 1   |          | *BOOT (REAR)                  | Bent      | 658.70 FL  | *658.70 FL |
| 3   | 1   |          | *BOOT LOCK (REAR)             | Dented    | 125.97 FL  | *125.97 FL |
| 4   | 1   |          | *BUMPER REFLECTOR (REAR LEFT) | Cracked   | 110.80 FL  | *110.80 FL |
| 5   | 1   |          | *PARKING SENSOR (REAR LEFT)   | Dented    | 130.00 FL  | *130.00 FL |
| 6   | 1   |          | *TAIL LAMP (LEFT)             | Cracked   | 277.00 FL  | *277.00 FL |
| 7   | 1   |          | *TOYOTA LOGO                  | Necessary | 52.15 FL   | *52.15 FL  |
| 8   | 1   |          | *VIOS LOGO                    | Necessary | 44.20 FL   | *44.20 FL  |
| 9   | 1   |          | *E LOGO                       | Necessary | 31.30 FL   | *31.30 FL  |
| 10  | 1   |          | *REAR BUMPER BRACKET          | Distorted | 63.70 FL   | *63.70 FL  |
| 11  | 1   |          | *REAR BUMPER RETAINER         | Cracked   | 92.33 FL   | *92.33 FL  |
| 12  | 1   |          | *BODY CLIPS                   | Necessary | 50.00 FS   | *50.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |          |          |
|---|----------|----------|
| Sub Total (\$\$)                                    | 2,093.65 | 2,093.65 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 510.91   | 510.91   |
| Total Parts (\$\$)                                  | 1,582.74 | 1,582.74 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars    | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                |          |                 |                 |
| 1                              | PANEL KNOCKING | New      | 1,600.00        | 700.00          |
| 2                              | SPRAY PAINTING | New      | 1,000.00        | 800.00          |
| <b>Gross Labour Cost (S\$)</b> |                |          | <b>2,600.00</b> | <b>1,500.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >