



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 8768Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER FASCIA	MTG CRACKED	648.90	435.00
1	O/S FRONT BUMPER SIDE RETAINER	DISTORTED	75.00	75.00
1	O/S FRONT FENDER	TO REPAIR SEE LABOUR	598.00	-
1	O/S FRONT FENDER INNER GARNISH	SERVICEABLE	175.80	-
10	O/S FRONT FENDER INNER GARNISH CLIP @\$5.00	NOT NECESSARY	50.00	-
1	N/S FRONT BUMPER FOG LAMP	SERVICEABLE	209.00	-
1	N/S FRONT BUMPER FOG LAMP COVER	SERVICEABLE	88.10	-
1	O/S HEAD LAMP	MTG CRACKED	606.20	606.20
	LESS 20% DISCOUNT		-490.20	-223.24
			1,960.80	892.96
	<u>LABOUR</u>			
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER .		680.00	300.00
	TO PUTTY AND SPRAY PAINTING.		680.00	400.00
	RE-SEAL ANTI RUST.	NOT NECESSARY	80.00	-
	TO CHECK,REPLACE ,REPAIR WIRING.		120.00	20.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,680.00	720.00
GRAND TOTAL			3,640.80	1,612.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/AGI21012075/Kvf3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.