

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012078/ETF3N2**Date:** 28/12/2021**REFERENCE**

Insured/Claimant: NG SWEE CHIA, EVON(HUANG RUI JIA, EVON)

Policy No: 7210137801

Date of Loss: 28/11/2021

Nature of Claim: OD

Claim No: 7304329564SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC7463U**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGMH710368

Reg. Date: 12/11/2021 (Man. Year: 2021)

Chassis No: KNAF3416MN5121087

Colour: Blue

Odometer: 565 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$90,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Kumho 5 mm

Rear Left Side:

Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side:

Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,274.00	2,044.80	1,229.20	37.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	3,920.00	950.00	19.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,144.00	5,964.80	2,179.20	26.76
+ GST 7.00/7.00% (S\$)	570.08	417.54	152.54	26.76
Nett Amount (S\$)	8,714.08	6,382.34	2,331.74	26.76

INSPECTION

Date of Assignment: 29/11/2021

Date Inspected: 29/11/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Crushed	243.00 F	*243.00 FL
2	1		*COVER-RR BUMPER LWR	Broken	193.00 F	*193.00 FL
3	1		*COVER-RR BUMPER UNDER,LH	Broken	33.00 F	*33.00 FL
4	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Not Necessary	181.00 F	*- FL
5	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 F	*- FL
6	1		*BRACKET-RR BPR UPR MTG	Not Necessary	84.00 F	*- FL
7	1		*BEAM-RR BUMPER	Broken	318.00 F	*318.00 FL
8	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 F	*- FL
9	1		*BRACKET-RR BEAM LWR,MTG (2 Pcs)	Crushed (1 Pc only)	14.00 F	*7.00 FL
10	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 F	*- FL
11	1		*STAY-RR BUMPER LH	Not Necessary	65.00 F	*- FL
12	1		*STAY-RR BUMPER RH	Not Necessary	65.00 F	*- FL
13	1		*BRACKET-ASSY RR BPR SIDE UPR,R	Not Necessary	26.00 F	*- FL
14	1		*BRACKET-ASSY RR BPR SIDE UPR,L	Not Necessary	31.00 F	*- FL
15	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 F	*- FL
16	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 F	*1,297.00 FL
17	1		*EMBLEM-KIA	Necessary	38.00 F	*38.00 FL
18	1		*EMBLEM-CERATO	Necessary	28.00 F	*28.00 FL
19	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
20	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
21	1		*PANEL ASSY-BACK Supplementary	Dented	324.00 F	*324.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,274.00	2,541.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	496.20
Total Parts (S\$)	3,274.00	2,044.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER,BOOTLID,REPAIR REAR END PANEL	New	1,200.00	600.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
4	SPRAY PAINT FOR REAR BUMPER,BOOTLID,REAR END PANEL	New	1,050.00	700.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
8	REPLACE REAR END PANEL,REPAIR LH REAR FENDER & RH REAR FENDER Supplementary	New	800.00	800.00
9	RESPRAY ON REAR END PANEL,LH REAR FENDER & RH REAR FENDER Supplementary	New	1,050.00	1,050.00
10	SUPPLY ONE SET OF REVERSE SENSOR Supplementary	New	220.00	220.00
Gross Labour Cost (\$\$)			4,870.00	3,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >