

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012091/GQY3N2**Date:** 07/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00194862000

Claimant Vehicle No : SBS8347Z **Insured Vehicle No :** SMT5037C

Date of Loss: 16/09/2021 Nature of Claim: TP Claim No: SNM21D205277/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS8347Z**

Make & Model: SCANIA KUB4X2, 8.9 D (A) Engine No: 6369486

Reg. Date: 22/09/2008 (Man. Year: 2008) Chassis No: YS2K4X20001861633

Colour: Multi-colour Odometer: 914389 km

Engine Capacity: 8867 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5 Rear Tyre Size: 275/70R22.5(D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	807.00	807.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,500.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,307.00	2,307.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	161.49	161.49	0.00	0.00
Nett Amount (\$\$)	2,468.49	2,468.49	0.00	0.00

INSPECTION

Date of Assignment: 29/11/2021

Date Inspected: 30/11/2021 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Mar 2022)	
Parts:	N/A	SCANIA KUB4X2 8.9 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS8347Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*WHEELARCH TRIM;N/S & O/S	Necessary	83.00 F	*83.00 F
2	1		*SIDE PANEL CR-ER.O/S.2.5MM ALUM	Buckled	339.00 F	*339.00 F
3	1		*SIDE PANEL ER-GR.O/S 2.5MM A/B/C SER8ES	Buckled	385.00 F	*385.00 F
Total Parts (S\$)						807.00
						807.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	1,500.00	1,500.00
Gross Labour Cost (\$\$)			1,500.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >