



Accident Reference & Bus No: **E/4027/2021 - SBS8347Z with SMT5037C**

Activated date: **Thu 25/11/2021 16:16**

Activated by: Seow Yong Hua <seowyh@sbstransit.com.sg>

Name of Surveyor: Guo Qiang

Company Name: LKK Auto

Date Surveyed: 30/11/2021

Estimate for

(A) Total for Parts:

Stock Code	Description	Quantity	Total Material cost(S\$)
30122034	WHEELARCH TRIM;N/S&O/S	2	\$83.00
30122062	SIDE PANEL CR~ER.O/S.2.5MM ALUM	1	\$339.00
30122040	SIDE PANEL ER~GR.O/S.2.5MM.A/B/C SERSES	1	\$385.00
(MO Number : BN2112000715)			Sub Total S\$: 807.00
(A)			Total for Parts S\$: 807.00

✓ NEC
✓ BUC
✓ BUC

- ☐ Parts cost: **\$ 807**
- ☐ Contractor Labour cost: **\$ 1500 + gst** ✓
- ☐ Workshop Labour cost: **not required by surveyor**
- ☐ Advertisement Cost: **\$0**
- ☐ Repair period: **2 days** ✓

Total: 2307

- ☐ Tow Cost: **\$0**
- ☐ Loss of use: **not required by surveyor**
- ☐ Overheads: **not required by surveyor**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____