

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012092/EGS3Q2**Date:** 15/03/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBE1922H	Insured Vehicle No :	SLV7066G
Date of Loss:	24/11/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE1922H		
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Engine No:	1KD2555875
Reg. Date:	25/09/2015 (Man. Year: 2015)	Chassis No:	JTFAT35YX0K205011
Colour:	Silver	Odometer:	107833 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,518.08	10,651.75	6,866.33	39.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,100.00	2,700.00	3,400.00	55.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,618.08	13,351.75	10,266.33	43.47
Approved Total (Overridden) (S\$)		8,400.00		
(S\$)	23,618.08	8,400.00	15,218.08	64.43
+ GST 7.00/7.00% (S\$)	1,653.27	588.00	1,065.27	64.43
Nett Amount (S\$)	25,271.35	8,988.00	16,283.35	64.43
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		9,348.00		

INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	09/12/2021	Inspected At: Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jan 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE1922H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	802.71 F	*802.71 FL
2	1		*BUMPER BRACKET	Not Necessary	342.23 F	*- FL
3	1		*RH DOOR	Dented	3,772.85 F	*3,772.85 FL
4	1		*RH WHEEL HOUSE COVER	Not Necessary	472.50 F	*- FL
5	1		*RH STEP	Broken	430.52 F	*430.52 FL
6	1		*RIGHT HEADLAMP ASSY	Cut	1,245.65 F	*1,245.65 FL
7	1		*DOOR HINGE UPPER	Not Necessary	129.06 F	*- FL
8	1		*DOOR HINGE LOWER	Not Necessary	129.06 F	*- FL
9	1		*COMPANY STICKER	Necessary	75.00 FS	*50.00 FS
10	1		*COMPANY REGISTRATION STICKER	Necessary	25.00 FS	*25.00 FS
11	1		*WHEEL ASSY DISC	Not Necessary	483.60 F	*- FL
12	1		*DISC FR RH BRAKE	Not Necessary	598.60 F	*- FL
13	1		*CALIPER & PAD ASSY ,FR BRAKE ,RH	Not Necessary	1,160.70 F	*- FL
14	1		*HUB ,FR RH WHEEL	Necessary	443.90 F	*443.90 FL
15	1		*KNUCKLE ASSY ,FR RH	Bent	706.20 F	*706.20 FL
16	1		*ARM ASSY ,FR SUSP ,UPR	Bent	1,160.20 F	*1,160.20 FL
17	1		*ARM ASSY ,FR SUSP ,LWR RH	Bent	1,029.80 F	*1,029.80 FL
18	1		*BALL JOINT ,FR SUSP LWR ARM	Bent	268.20 F	*268.20 FL
19	1		*STEERING RACK ASSY	Broken	4,242.30 F	*4,242.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,518.08	14,177.33
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	3,525.58
Total Parts (\$)	17,518.08	10,651.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	800.00	700.00
2	TYRE REALIGNMENT	New	300.00	200.00
3	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGNMENT ,ETC	New	2,000.00	900.00
4	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGNMENT ETC	New	3,000.00	900.00
Gross Labour Cost (S\$)			6,100.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >