

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012094/AVY3N2**Date:** 11/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00081062102

Claimant Vehicle No : SKH2869A **Insured Vehicle No :** YP3670R

Date of Loss: 26/11/2021 Nature of Claim: TP Claim No: SNM21D206872/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH2869A**

Make & Model: PORSCHE MACAN, 2.0 PDK CYP E6 (A) Engine No: 097700

Reg. Date: 23/03/2018 (Man. Year: 2017) Chassis No: WP1ZZZ95ZJLB06151

Colour: Silver Odometer: 24425 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,646.00	12,323.40	10,322.60	45.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,410.00	1,070.00	43.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,126.00	13,733.40	11,392.60	45.34
Approved Total (Overridden) (\$\$)		10,900.00		
Nett Amount (\$\$)	25,126.00	10,900.00	14,226.00	56.62

INSPECTION

Date of Assignment: 29/11/2021

Date Inspected: 30/11/2021 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2022)
Parts:	M1-SUV	PORSCHE MACAN 2.0 PDK CYP E6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH2869A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,985.00 F	*2,985.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	278.00 F	*278.00 FL
4	1		*FRONT BUMPER AIR GUIDE LH	Cut	259.00 F	*259.00 FL
5	1		*FRONT BUMPER SIDE GRILLE LH	Not Necessary	731.00 F	*- FL
6	1		*FRONT BUMPER SIGNAL LAMP LH	Not Necessary	349.00 F	*- FL
7	1		*HEADLAMP LH	Cracked	5,099.00 F	*5,099.00 FL
8	1		*BONNET	Dented	3,058.00 F	*3,058.00 FL
9	1		*BONNET LOGO	Necessary	297.00 F	*297.00 FL
10	1		*BONNET LOCK	Not Necessary	288.00 F	*- FL
11	1		*FRONT LH INNER SHIELD	Not Necessary	369.00 F	*- FL
12	1		*FRONT LH INNER SHIELD CLIPS	Not Necessary	30.00 F	*- FL
13	1		*FRONT LH SHOCK ABSORBER	Not Necessary	1,624.00 F	*- FL
14	1		*FRONT LH KNUCKLE ARM	Not Necessary	1,890.00 F	*- FL
15	1		*FRONT LH LOWER ARM	Not Necessary	1,090.00 F	*- FL
16	1		*FRONT LH WHEEL HUB C/W BEARING	Not Necessary	529.00 F	*- FL
17	1		*FRONT LH WHEEL RIM	Cut	3,120.00 FS	*1,500.00 FS
18	1		*FRONT LH TYRE	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,646.00	13,526.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,202.60
Total Parts (\$)	22,646.00	12,323.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	700.00	550.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	0.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	380.00	0.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO PERFORM DIAGNOSTIC TEST	New	250.00	150.00
Gross Labour Cost (\$\$)			2,480.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >