

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012098/VPS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210015528
Claimant Vehicle No :	SHD1176D	Insured Vehicle No :	SKR132C
Date of Loss:	28/11/2021	Nature of Claim:	TP
		Claim No:	3803569422SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1176D	Engine No:	D4FDEH313360
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5593517
Reg. Date:	18/05/2015 (Man. Year: 2014)	Odometer:	837859 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,678.80	6,002.30	4,676.50	43.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,690.00	1,290.00	43.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,658.80	7,692.30	5,966.50	43.68
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	13,658.80	6,150.00	7,508.80	54.97
+ GST 7.00/7.00% (S\$)	956.12	430.50	525.62	54.97
Nett Amount (S\$)	14,614.92	6,580.50	8,034.42	54.97
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$67.41/day) (S\$)		337.05		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,169.55		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	29/11/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET GRILLE	Scratched	385.00 FL	*385.00 FL
2	1		*FRONT N/S & O/S HEAD LAMPS	O/S Cut / N/S Serviceable	2,056.00 FL	*1,028.00 FL
3	1		*FRONT BUMPER	Cut	531.00 FL	*531.00 FL
4	1		*FRONT BUMPER UPPER REINFORCEMENT	Serviceable	40.00 FL	*- FL
5	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
6	1		*FRONT BUMPER CENTRE GRILLE	Distorted	174.00 FL	*174.00 FL
7	1		*FRONT BUMPER LOWER STIFFER	Serviceable	134.00 FL	*- FL
8	1		*FRONT BUMPER TOW HOOK COVER	Distorted	14.00 FL	*14.00 FL
9	1		*FRONT BUMPER INNER SPONGE	Serviceable	110.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	328.00 FL	*328.00 FL
11	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
12	2		*FRONT BUMPER N/S & O/S UPPER BRACKET	Necessary	32.00 FL	*32.00 FL
13	2		*FRONT BUMPER N/S & O/S SUPPORT BRACKET	Necessary	32.00 FL	*32.00 FL
14	1		*FRONT BUMPER N/S & O/S PROTECTOR	O/S Deformed / N/S Serviceable	102.00 FL	*51.00 FL
15	1		*FRONT BUMPER N/S & O/S FOG LIGHT COVER	O/S Distorted / N/S Serviceable	132.00 FL	*66.00 FL
16	1		*BOOT LID	Repair	1,119.00 FL	*- FL
17	1		*BOOT LID LOCK	Serviceable	99.00 FL	*- FL
18	1		*BOOTLID LOCK CABLE	Serviceable	35.00 FL	*- FL
19	1		*BOOTLID STRIKER	Serviceable	21.00 FL	*- FL
20	1		*BOOTLID EMBLEM	Serviceable	27.00 FL	*- FL
21	1		*BOOTLID CRDI	Serviceable	29.00 FL	*- FL
22	1		*BOOT LID RUBBER WEATHERSTRIP	Deformed	96.00 FL	*96.00 FL
23	1		*BOOT LID LOWER GARNISH	Repair	290.00 FL	*- FL
24	2		*BOOTLID HINGES	Serviceable	132.00 FL	*- FL
25	1		*BOOTLID INNER TRIM	Serviceable	190.00 FL	*- FL
26	1		*END PANEL INNER GARNISH	Distorted	74.00 FL	*74.00 FL
27	1		*REAR BUMPER	Cut	696.00 FL	*696.00 FL
28	1		*REAR BUMPER LOWER COVER	Dented	206.00 FL	*206.00 FL
29	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Necessary	58.00 FL	*58.00 FL
30	1		*REAR BUMPER INNER SPONGE	Cut	114.00 FL	*114.00 FL
31	1		*REAR BUMPER REINFORCEMENT	Dented	607.00 FL	*607.00 FL
32	2		*REAR BUMPER STAY O/S & N/S	Cracked	108.00 FL	*108.00 FL
33	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Necessary	36.00 FL	*36.00 FL
34	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Necessary	36.00 FL	*36.00 FL
35	2		*REAR BUMPER REFLECTOR N/S & O/S	Serviceable	92.00 FL	*- FL
36	2		*REAR N/S & O/S TAIL LAMP	Serviceable	842.00 FL	*- FL
37	2		*BOOTLID N/S & O/S REFLECTOR	Serviceable	700.00 FL	*- FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
39	1		*FRONT NO PLATE WITH CASING	Scratched	50.00 FS	*50.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
41	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
42	1		*SET BOOTLID INNER TRIM CLIPS	Serviceable	52.00 FS	*- FS
43	1		*SET BOOTLID LOWER GARNISH CLIPS	Necessary	60.00 FS	*60.00 FS
44	1		*SET BOOTLID STICKERS	Necessary	100.00 FS	*80.00 FS
45	1		*SET REVERSE SENSOR	Cut	280.00 FS	*280.00 FS
46	1		*REAR NO PLATE WITH CASING	Serviceable	50.00 FS	*- FS
47	1		*SUNDRY	Serviceable	50.00 FS	*- FS
48	1		*END PANEL	Dented	250.00 FL	*250.00 FL
49	1		*EXHAUST PIPE	Dented	1,009.00 FL	*1,009.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,780.00 6,603.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,101.20	600.70
Total Parts (S\$)					10,678.80	6,002.30
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FOR WIRING AND FOCUS HEAD LAMPS	New	80.00	30.00
2	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	40.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT STRAIGHTEN REPAIR RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	1,400.00	720.00
5	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL,FRONT BUMPER	New	1,000.00	720.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	30.00
7	TO DISMANTLE /REPLACE NEW EXHAUST PIPE	New	120.00	120.00
Gross Labour Cost (\$\$)			2,980.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >