

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012099/BGA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMQ5974M **Insured Vehicle No :** SLQ8099G
 Date of Loss: 29/11/2021 Nature of Claim: TP Claim No: MFL2021D0005226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ5974M**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4027395
 Reg. Date: 13/01/2016 (Man. Year: 2015) Chassis No: RU11107390
 Colour: White Odometer: 99294 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Viking 6 mm Rear Left Side: Viking 6 mm
 Front Right Side: Viking 6 mm Rear Right Side: Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,577.15	2,569.44	5,007.71	66.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,660.00	1,260.00	43.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,497.15	4,229.44	6,267.71	59.71
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	10,497.15	3,350.00	7,147.15	68.09
+ GST 7.00/7.00% (S\$)	734.80	234.50	500.30	68.09
Nett Amount (S\$)	11,231.95	3,584.50	7,647.45	68.09
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,241.95		

INSPECTION

Date of Assignment: 29/11/2021
 Date Inspected: 30/11/2021 Inspected At: 8 KAKI BUKIT AVE 4 PREMIER #01-49
 Estimated Period of Repair: 6.0 days Repairer: Bifrost Auto Pte Ltd (Beach Road)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5974M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	953.30 FL	*953.30 FL
2	1		*TAILGATE VEZEL EMBLEM	Necessary	56.30 FL	*46.00 FL
3	1		*TAILGATE WINDSCREEN GLASS UPPER RUBBER MOULDING	Necessary	52.00 FL	*52.00 FL
4	1		*TAILGATE WINDSCREEN GLASS LOWER RUBBER MOULDING	Necessary	52.00 FL	*52.00 FL
5	1		*TAILGATE WINDSCREEN GLASS RH RUBBER MOULDING	Necessary	52.00 FL	*52.00 FL
6	1		*TAILGATE WINDSCREEN GLASS LH RUBBER MOULDING	Necessary	52.00 FL	*52.00 FL
7	1		*TAILGATE LH LAMP	Not Necessary	413.30 FL	*- FL
8	1		*TAILGATE LH LAMP GASKET	Not Necessary	38.50 FL	*- FL
9	1		*TAILGATE RH LAMP	Not Necessary	413.30 FL	*- FL
10	1		*TAILGATE RH LAMP GASKET	Not Necessary	38.50 FL	*- FL
11	1		*TAILGATE OUTER GARNISH	Not Damaged	231.00 FL	*- FL
12	1		*TAILGATE OUTER GARNISH EMBLEM	Necessary	29.00 FL	*29.00 FL
13	1		*TAILGATE REVERSE CAMERA	Not Damaged	1,020.74 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Broken	154.70 FL	*154.70 FL
15	1		*TAILGATE LOCK	Jammed	189.00 FL	*189.00 FL
16	1		*TAILGATE LOCK CATCH	Not Necessary	27.50 FL	*- FL
17	1		*TAILGATE INNER PULL HANDLE	Not Damaged	27.50 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Torn	96.80 FL	*96.80 FL
19	1		*REAR BUMPER	Dented	465.70 FL	*465.70 FL
20	1		*REAR BUMPER LOWER COVER	Broken	251.00 FL	*251.00 FL
21	1		*REAR BUMPER LH REFLECTOR	Not Damaged	141.10 FL	*- FL
22	1		*REAR BUMPER LH SIDE COVER	Broken	198.00 FL	*198.00 FL
23	1		*REAR BUMPER LH SIDE RETAINER	Necessary	26.50 FL	*26.50 FL
24	1		*REAR BUMPER RH REFLECTOR	Not Damaged	141.10 FL	*- FL
25	1		*REAR BUMPER RH SIDE COVER	Not Damaged	198.00 FL	*- FL
26	1		*REAR BUMPER RH SIDE RETAINER	Necessary	26.50 FL	*26.50 FL
27	1		*LH TAILLAMP	Not Damaged	487.60 FL	*- FL
28	1		*LH TAILLAMP GASKET	Not Damaged	44.20 FL	*- FL
29	1		*RH TAILLAMP	Not Damaged	487.60 FL	*- FL
30	1		*RH TAILLAMP GASKET	Not Damaged	44.20 FL	*- FL
31	1		*END PANEL	Repair	415.60 FL	*- FL
32	1		*END PANEL INNER GARNISH	Broken	109.00 FL	*92.30 FL
33	1		*END PANEL ANTENNA SENSOR	No such part	65.10 FL	*- FL
34	1		*END PANEL BUZZER SENSOR	No such part	85.60 FL	*- FL
35	1		*REAR COMPARTMENT PANEL TRAY GARNISH	Not Damaged	485.90 FL	*- FL
36	1		*REAR COMPARTMENT PANEL TRAY GARNISH TOP COVER BOARD	Not Damaged	430.30 FL	*- FL
37	1		*REAR LH FENDER ARCH MOULDING	Not Damaged	198.00 FL	*- FL
38	1		*REAR RH FENDER ARCH MOULDING	Not Damaged	198.00 FL	*- FL
39	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
40	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

6/10/22, 8:29 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
42	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
44	1		*SET REAR BUMPER REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
45	1		*SET REAR FENDER RH ARCH MOULDING CLIPS	Not Necessary	70.00 FS	*- FS
46	1		*SET REAR FENDER LH ARCH MOULDING CLIPS	Not Necessary	70.00 FS	*- FS
47	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
48	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					9,256.44	3,116.80
- List Item Discount on L Items 20.00/20.00% (S\$)					1,679.29	547.36
Total Parts (S\$)					7,577.15	2,569.44
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	70.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER COMPONENTS TO ASSIST REPAIR	New	180.00	80.00
7	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	70.00	60.00
9	REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH AND BOARDS TO ASSIST REPAIR	New	220.00	0.00
Gross Labour Cost (\$)			2,920.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >