

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012100/RPA3Q2**Date:** 21/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100500708
Claimant Vehicle No :	SNA7808U	Insured Vehicle No :	SLL1171C
Date of Loss:	22/11/2021	Nature of Claim:	TP
		Claim No:	9627083466SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA7808U	Engine No:	L15B6023942
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GKB2103392
Reg. Date:	13/07/2021 (Man. Year: 2019)	Odometer:	45524 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,014.98	4,236.96	5,778.02	57.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,540.00	600.00	28.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,154.98	5,776.96	6,378.02	52.47
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	12,154.98	4,600.00	7,554.98	62.16
+ GST 7.00/7.00% (S\$)	850.85	322.00	528.85	62.16
Nett Amount (S\$)	13,005.83	4,922.00	8,083.83	62.16
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,484.00		

INSPECTION

Date of Assignment:	29/11/2021	
Date Inspected:	30/11/2021	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,900.20 FL	*1,900.20 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	30.10 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	30.10 FL	*- FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	25.40 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	64.60 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	64.60 FL	*- FL
7	1		*REAR TAILGATE	Bent	2,200.60 FL	*2,200.60 FL
8	1		*REAR TAILGATE LAMP RH	Not Necessary	580.10 FL	*- FL
9	1		*REAR TAILGATE LAMP LH	Not Necessary	580.10 FL	*- FL
10	1		*REAR TAILGATE INNER BOARD	Not Necessary	438.10 FL	*- FL
11	1		*REAR TAILGATE RUBBER	Necessary	140.60 FL	*140.60 FL
12	1		*REAR TAILGATE LOCK	Not Necessary	287.10 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	210.50 FL	*- FL
14	1		*REAR END PANEL	Bent	468.20 FL	*468.20 FL
15	1		*REAR BUMPER BRACKET RH	Not Necessary	56.20 FL	*- FL
16	1		*REAR BUMPER BRACKET LH	Not Necessary	56.20 FL	*- FL
17	1		*REAR TAILGATE UNDERCOVER	Not Necessary	100.20 FL	*- FL
18	1		*REAR TAILGATE HINGE RH	Not Necessary	59.60 FL	*- FL
19	1		*REAR TAILGATE HINGE LH	Not Necessary	59.60 FN	*- FN
20	1		*REAR TAILGATE DAMPER RH	Not Necessary	186.70 FL	*- FL
21	1		*REAR TAILGATE DAMPER LH	Not Necessary	196.70 FL	*- FL
22	1		*REAR TAILLAMP RH	Not Necessary	540.80 FL	*- FL
23	1		*REAR TAILLAMP LH	Not Necessary	540.80 FL	*- FL
24	1		*REAR SPARE TYRE PANEL	Not Necessary	1,901.50 FL	*- FL
25	1		*REAR SPARE TYRE COMPARTMENT BOX	Not Necessary	459.80 FL	*- FL
26	1		*REAR END PANEL TOP CHROME	Cracked	188.60 FL	*188.60 FL
27	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
28	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*30.00 FS
29	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
30	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
31	1		*REAR TAILGATE INNER BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
32	1		*REAR BUMPER SENSOR	Not Necessary	200.00 FS	*- FS
33	1		*REAR END PANEL TOP GARNISH	Deformed	210.50 FL	*210.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	12,327.50	5,258.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,303.58	1,021.74
- Nett Item Discount on N Items 15.00/15.00% (\$\$)	8.94	0.00

Total Parts (\$\$)	10,014.98	4,236.96
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	100.00	60.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	60.00
3	TO TRANSFER REAR TAILGATE	New	80.00	60.00
4	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
5	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS	New	30.00	0.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	800.00	600.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	100.00	60.00
8	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	750.00	600.00
9	TO CARRY -OUT BODY CAVITY PRESERVATION	New	100.00	0.00
Gross Labour Cost (S\$)			2,140.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >