

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	AL INSURANCE LTD		Ref:	CS3/FCI21012101/Ea3e2
	36 ROBINSON RO SINGAPORE 0688		Date:	23/12/2021	
				Code:	FCI2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YQ 727B	Veh. Inspected		YM 8041P
	Policy No.		Coverage (\$)		0.00
	Claim No.	D21003300MFCV	Excess (\$)		0.00
	Assign From		Assign Date		29/11/2021
2.	Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FE83BE6SRDEA	c.c		2977
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	FE83BEA10639	Colour		WHITE
	Odometer	457790 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	FAIR			
3.	. Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	7.00-16	BRIDGESTONE		4 mm
	L/H Front Tyre	7.00-16	BRIDGESTONE		4 mm
	R/H Rear Tyre	7.00-16	BRIDGESTONE		4 mm
	L/H Rear Tyre	7.00-16	BRIDGESTONE		4 mm
4.	Description of Damages				
	THE VEHICLE SU	USTAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information				
	Accident Date	22/11/2021	Inspect Date /	Time	15/12/2021 (10:27 AM)
	Survey held at	MILLION AUTO SERVICE			
		4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$11,000.00				

Report Ref No. CS3/FCI21012101/Ea3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

HEN 15UE TEE

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser