



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303630

INV Date 08/06/2023

Reference CC4/LPC21012102/Dpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 2112M
Insured Veh. GBF 6629S
Claim No. 21/21/21/VC00/025184
Policy No. Z/21/VC00/109671
Accident Date 23/11/2021
Inspection Date 30/11/2021

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (8%)	28.00
Grand Total	378.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21012102/Dpa3q2 Date: 08/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 6629S	Veh. Inspected	SMT 2112M
	Policy No.	Z/21/VC00/109671	Coverage (\$)	0.00
	Claim No.	21/21/21/VC00/025184	Excess (\$)	0.00
	Assign From		Assign Date	29/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 730LI SR	c.c	2019
	Engine No.	HIDDEN	Year of Reg.	1998
	Chassis No.	WBA7T02030BS88858	Colour	GREY
	Odometer	49424 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	PIRELLI	5 mm
	L/H Front Tyre	245/45 R19	PIRELLI	5 mm
	R/H Rear Tyre	245/45 R19	PIRELLI	5 mm
	L/H Rear Tyre	245/45 R19	PIRELLI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/11/2021	Inspection Date	30/11/2021
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 2112M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	2,506.90	2,506.90
1	BONNET LOGO	NECESSARY	118.60	118.60
2	BONNET LOCK ASSY	JAMMED/ BENT	386.60	193.30
1	BONNET LOCK BRACKET	NOT NECESSARY	253.40	-
1	FRONT BUMPER	CRACKED / DEFORMED	2,189.60	1,501.35
1	FRONT BUMPER SIDE RETAINER UPPER RH	CRACKED / DEFORMED	84.00	84.00
1	FRONT BUMPER SIDE RETAINER LOWER RH	NOT NECESSARY	72.60	-
1	FRONT BUMPER SIDE CARRIER	CRACKED / DEFORMED	178.00	178.00
2	FRONT BUMPER BRACKET	NOT NECESSARY	680.00	-
1	FRONT BUMPER INNER SPONGE	CRACKED	289.50	289.50
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,100.00	-
2	FRONT BUMPER REINFORCEMENT BRACKET	NOT NECESSARY	290.00	-
1	FRONT BUMPER LOWER REINFORCEMENT	CRACKED/ DEFORMED	310.60	310.60
1	FRONT BUMPER LOWER GRILLE	CRACKED / DEFORMED	630.00	630.00
1	FRONT BUMPER LOWER GRILLE OUTER CHROME	CRACKED/ DEFORMED	180.00	180.00
1	FRONT BUMPER SIDE LOWER GRILLE RH	CRACKED / DEFORMED	240.00	240.00
1	FRONT BUMPER SIDE LOWER GRILLE OUTER CHROME RH	CRACKED / DEFORMED	180.00	180.00
1	FRONT BUMPER OUTER CHROME GARNISH RH	CRACKED / DEFORMED	180.00	180.00
1	FRONT BUMPER TOW CAP	MISSING	89.00	89.00
4	FRONT BUMPER PARKING SENSOR	CRACKED (1 PCS ONLY)	840.00	210.00
2	FRONT GRILLE	NOT NECESSARY	977.20	-
1	FRONT GRILLE OUTER CHROME	CRACKED / DEFORMED	345.00	345.00
1	FRONT GRILLE BASE	NOT NECESSARY	883.90	-
1	FRONT FENDER RH	BUCKLED	1,930.50	1,930.50

Report Ref No. CC4/LPC21012102/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER INNER COWLING RH	DEFORMED / TORN	436.40	436.40
1	FRONT FENDER INNER AIR DUCTS RH	NOT NECESSARY	186.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,889.20	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	339.00	-
1	HEADLAMP RH	CRACKED	8,470.00	5,947.00
1	HEADLAMP BALLAST RH	MALFUNCTION	655.00	655.00
1	HEADLAMP LOWER BRACKET RH	SERVICEABLE	180.00	-
1	FRONT ENGINE COVER	DEFORMED / TORN	248.00	248.00
1	FRONT ABSORBER RH	BENT	4,100.00	3,500.00
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	950.00	-
1	FRONT KNUCKLE ARM BEARING RH	NOT NECESSARY	685.00	-
1	FRONT LOWER ARM RH	BENT	595.00	595.00
1	FRONT TRUST ARM RH	BENT	415.00	415.00
	LESS 5% DISCOUNT		-1,704.20	-1,048.16
			32,379.80	19,914.99
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BONNET SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT BUMPER CLIPS (SN)	CRACKED / DEFORMED	60.00	30.00
1	FRONT BUMPER LOWER GRILLE (SN)	NOT NECESSARY	60.00	-
6	FRONT BUMPER PARKING SENSOR (SN)	NECESSARY	120.00	120.00
1	FRONT GRILLE (SN)	NOT NECESSARY	60.00	-
1	FRONT FENDER SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT FENDER INNER COWLING CLIPS (SN)	CRACKED / DEFORMED	60.00	30.00
1	FRONT ALLOY RIM (LOCAL REPAIR) (SN)	GRAZED / DENTED	1,150.00	200.00
1	FRONT TYRE (SN)	NOT NECESSARY	580.00	-
			2,370.00	380.00
	<u>LABOUR</u>			
	R&R FRONT BUMPER PARKING SENSOR .		100.00	60.00
	R&R FRONT UNDER CARRIAGE.		450.00	150.00
	R&R FRONT TYRE & BALACING.	NOT NECESSARY	100.00	-

Report Ref No. CC4/LPC21012102/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WHEEL ALIGNMENT.		180.00	60.00
	UPHOLSTERY .	NOT NECESSARY	200.00	-
	PROGRAMMING HEADLAMP CONTROL UNIT.		300.00	200.00
	DIAGNOSTIC RESET FAULT CODE.		300.00	120.00
	UPHOLSTERY .	NOT NECESSARY	200.00	-
	CHECK WIRING .		100.00	50.00
	PANEL BEATING.		1,600.00	1,000.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,600.00	600.00
			5,330.00	2,240.00
GRAND TOTAL			40,079.80	22,534.99

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,000.00
---	--	--	------------------

Report Ref No. CC4/LPC21012102/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2112M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2112M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

