

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012103/R1QF3E2

Date: 16/02/2022

REFERENCE

Insured/Claimant: MOHAMED YUSRI BIN MOHAMED YUSOF
Date of Loss: 29/11/2021

Policy No: 7210038551

Nature of Claim: OD Claim No: 3821935867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ4316Y**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11CQ8847
Reg. Date: 27/04/2021 (Man. Year: 2020) Chassis No: GF7W0700793
Colour: Grey Odometer: 9592 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,229.24	1,754.81	2,474.43	58.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,225.00	1,425.00	39.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,879.24	3,979.81	3,899.43	49.49
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,579.24	3,679.81	3,899.43	51.45
+ GST 7.00/7.00% (S\$)	530.55	257.59	272.96	51.45
Nett Amount (S\$)	8,109.79	3,937.40	4,172.39	51.45

INSPECTION

Date of Assignment: 30/11/2021

Date Inspected: 06/01/2022 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*PANEL ASSY, FR DOOR, LH	Bent	930.00 FL	*930.00 FL
3	1		*MLDG, F/DR WDO BELT LINE, LH	Not Necessary	130.00 FL	*- FL
4	1		*HINGE, FR DOOR, UPP LH	Not Necessary	43.00 FL	*- FL
5	1		*HINGE, FR DOOR, LWR LH	Not Necessary	43.00 FL	*- FL
6	1		*LATCH, FR DOOR, LH	Not Necessary	322.00 FL	*- FL
7	1		*STRIKER, FR DOOR LATCH	Not Necessary	20.00 FL	*- FL
8	1		*CHECK, FR DOOR	Not Necessary	31.00 FL	*- FL
9	1		*PANEL ASSY, RR DOOR, LH	Bent	851.00 FL	*851.00 FL
10	1		*MLDG, R/DR WDO BELT LINE, LH	Not Necessary	124.00 FL	*- FL
11	1		*HINGE, RR DOOR, UPR LH	Not Necessary	43.00 FL	*- FL
12	1		*HINGE, RR DOOR, LWR LH	Not Necessary	43.00 FL	*- FL
13	1		*W/STRIP, RR DOOR OPNG, FR LH	Not Necessary	127.00 FL	*- FL
14	1		*TAPE, FR DOOR SASH, LH	Necessary	42.00 FL	*42.00 FL
15	1		*TAPE, RR DOOR SASH	Necessary	42.00 FL	*42.00 FL
16	1		*TAPE, RR DOOR SASH	Necessary	42.00 FL	*42.00 FL
17	1		*GARNISH, FR DOOR, LH	Scratched	182.00 FL	*182.00 FL
18	1		*GARNISH, RR DOOR, LH	Scratched	164.00 FL	*164.00 FL
19	1		*AIR DAM, SIDE, LH	Not Necessary	304.00 FL	*- FL
20	1		*MOULDING, FR WHEEL ARCH, LH	Not Necessary	168.00 FL	*- FL
21	1		*MOULDING, RR WHEEL ARCH, LH	Not Necessary	168.00 FL	*- FL
22	1		*BODY KIT, OUTLANDER	Repair	1,554.00 FN	*- F
23	1		*W/STRIP, R/DR OPN, LWR OTR L	Not Necessary	33.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	5,426.00	2,273.00
- List Item Discount on L Items 23.00/23.00% (\$)	885.96	518.19
- Nett Item Discount on N Items 20.00/0.00% (\$)	310.80	0.00
Total Parts (\$)	4,229.24	1,754.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHF DOOR & LHR DOOR. REPAIR LHR FENDER	New	1,800.00	900.00
2	RESPRAY LHF DOOR, LHR DOOR, LHR FENDER & LH SIDE SKIRT	New	1,400.00	875.00
3	REMOVE & REFIT LHF DOOR COMPONENT	New	120.00	120.00
4	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	SUPPLY BODY PNL SEALANT	New	60.00	60.00
			Gross Labour Cost (\$)	2,225.00
			3,650.00	2,225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >