



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7494G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE	BENT	80.00	30.00
2	REAR NUMBER PLATE LAMPS	BROKEN	182.00	96.00
1	REAR NUMBER PLATE BRACKET	BENT	180.00	58.00
1	REAR CHECKER PLATE PLATFORM	NOT DAMAGED	12,500.00	-
6	REAR CHECKER PLATE PLATFORM ROLLERS	NOT DAMAGED	1,500.00	-
6	SETS REAR CHECKER PLATE PLATFORM ROLLERS BEARINGS	NOT DAMAGED	720.00	-
1	RH TAILLAMP	NOT DAMAGED	580.00	-
1	LH TAILLAMP	NOT DAMAGED	580.00	-
1	WHEEL LIFT "T" ARM	BENT	4,800.00	4,800.00
2	WHEEL LIFT "T" ARM RH TOW TROLLEY @\$780.00	BENT	1,560.00	1,560.00
2	WHEEL LIFT "T" ARM LH TOW TROLLEY @\$780.00	BENT	1,560.00	1,560.00
1	WHEEL LIFT T ARM INNER MEMBER LH LIFTING HYDRAULIC CYLINDERS	NOT DAMAGED	2,200.00	-
1	SET WHEEL LIFT T ARM INNER MEMBER LH LIFTING HYDRAULIC CYLINDERS PRESSURE HOSE	NOT DAMAGED	750.00	-
1	WHEEL LIFT T ARM INNER MEMBER RH LIFTING HYDRAULIC CYLINDERS	NOT DAMAGED	2,200.00	-
1	SET WHEEL LIFT T ARM INNER MEMBER RH LIFTING HYDRAULIC CYLINDERS PRESSURE HOSE	NOT DAMAGED	750.00	-
1	WHEEL LIFT T ARM INNER MEMBER	NOT DAMAGED	2,800.00	-
1	WHEEL LIFT T ARM INNER MEMBER EXTENABLE HYDRAULIC CYLINDER	NOT DAMAGED	2,800.00	-
1	WHEEL LIFT T ARM INNER MEMBER EXTENABLE HYDRAULIC CYLINDER KING PIN	NOT DAMAGED	320.00	-
1	SET WHEEL LIFT T ARM INNER MEMBER EXTENABLE HYDRAULIC CYLINDER PRESSURE HOSE	NOT DAMAGED	750.00	-
1	DRUM HYDRAULIC CYLINDER FLUID	NOT NECESSARY	480.00	-
	LESS 15% DISCOUNT		-	-1,215.60
			37,292.00	6,888.40
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS.		3,500.00	800.00

Report Ref No. CS/INC21012106/Btf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED PANELS.		1,500.00	400.00
	CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	350.00	-
	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS.	NOT NECESSARY	100.00	-
			5,450.00	1,200.00
GRAND TOTAL			42,742.00	8,088.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			6,450.00
---	--	--	----------

Report Ref No. CS/INC21012106/Btf3e2

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.