

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS3/INC21012107/Gvf3e2
	73 BRAS BASAH R UNION HOUSE SIN	ROAD #05-01 NTUC TRADE NGAPORE 189556		Date:	07/12/2021
	ATTN: CYNDIIE YO	ONG		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SNA 2260G	Veh. Inspected		SLG 7000A
	Policy No.	olicy No.			0.00
	Claim No.	MT/1152798-001	Excess (\$)		0.00
	Assign From	LIM CHAN HENG	Assign Date		30/11/2021
2. Vehicle Particulars & Condition					
	Make & Model	AUDI TT COUPE 2.0	c.c		1984
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	TRUZZZFV5F1007717	Colour		WHITE
	Odometer	91837 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/35Z R19	DUNLOP		6 mm
	L/H Front Tyre	245/35Z R19	DUNLOP		6 mm
	R/H Rear Tyre	245/35Z R19	DUNLOP		6 mm
	L/H Rear Tyre	245/35Z R19	DUNLOP		6 mm
4. Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE	STAINED DAMAGES AT THE FRONT N/S PORTION AND			
5.	General Information				
	Accident Date	26/11/2021	Inspect Date /	Time	30/11/2021 (03:30 PM)
	Survey held at	GARAGE 13 PTE LTD			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC21012107/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor