

哈汽車貿易服務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3046/11/21

Your Ref:

Date: 29th NOV 2021

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Name Of Insured : Joe's Seafood Trading
Date Of Accident : 28/11/21 (13:16hrs)
Policy Number : D21MCV0007106

Estimate cost of repair to TOYOTA DYNA (A) 3.0 Lorry - GBK 6215 B

1 pc front bumper	D/S	\$ 683.90	✓
2 pcs front bumper o/s & n/s bracket	n/s o/s	\$ 211.60	o/s n/s 423.20 1pc
1 pc front bumper n/s fog lamp assy	3/ro	\$ 299.30	✓
1 pc front centre cross bar member	R	\$ 264.40	X
1 pc front n/s tow bar bracket	R	\$ 128.80	X
1 pc front number plate	one	\$ 60.00	20 s/n
2 pcs o/s & n/s head lamp assy	n/s one o/s n/s	\$ 895.10	1,790.20 1pc
2 pcs o/s & n/s head lamp lower bracket	n/s one	\$ 41.20	82.40 1pc
1 pc front n/s corner panel	n	\$ 288.40	X
1 pc front centre panel	Body to	\$ 1,226.60	✓
1 pc front centre grille panel	one	\$ 650.50	✓
8 pcs front centre grille panel clips	n/s	\$ 8.20	65.60
1 pc front centre top grille (logo)	5/2 (Black)	\$ 170.40	✓
6 pcs front centre top grille clips stopper	6.20 n/s	\$ 37.20	✓
1 pc front centre top grille logo emblem	5/2	\$ 70.40	✓
1 pc front centre lower panel 'DYNA' emblem	n/s	\$ 60.70	✓
1 pc front o/s door	DD	\$ 1,349.40	✓
2 pcs front o/s door top & low hinge	7/1	\$ 81.40	162.80
1 pc front o/s door checker	7/1	\$ 127.80	✓
2 pcs front o/s & n/s door black sticker	ROG	\$ 45.00	90.00
2 pcs front o/s & n/s door signal lamp assy	81.10 o/s one	\$ 162.20	1pc o/s one
1 pc front o/s door weatherstrip	n/s	\$ 186.40	✓
1 pc front o/s door inner trim board cover	11	\$ 491.50	X
20 pcs front o/s door inner trim board clips	6.20 11	\$ 124.00	X
1 pc front o/s door audio speaker	11	\$ 262.20	X
1 pc front o/s door power window regulator	11	\$ 295.60	X
1 pc front o/s door inner lock	JM	\$ 285.90	✓
1 pc front o/s door pillar panel	R	\$ 392.20	X
1 pc front windscreen glass weatherstrip	11	\$ 288.60	X
1 pc front o/s step garnish	2/1/2/3	\$ 318.30	X
1 pc front o/s wheel panel	R	\$ 390.50	X
1 pc front o/s wheel panel rubber seal	7/1	\$ 36.20	✓
8 pcs front o/s wheel panel clips	11	\$ 4.50	36.00 X
1 pc o/s wheel mudguard garnish	2/2	\$ 179.90	✓
1 pc radiator spare tank	2/2	\$ 133.30	✓
1 pc air cleaner box	one	\$ 671.80	✓
1 pc air cleaner cover	complete	\$ 76.10	X
1 pc air filter	M/S	\$ 71.20	✓
1 pc fuel tank	R	\$ 774.40	X
1 pc o/s tail gate door combination bracket	R	\$ 198.70	X
1 pc o/s tail gate door combination bush	M/S	\$ 32.20	✓

\$ 13,439.20

Balance C/F.....

813880

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3046/11/21

Your Ref: _____

Date: 29th NOV 2021

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD., Balance B/F... \$ 13,439.20

1 pc front o/s wheel rim	454.40	80 s/w
1 pc front o/s tyre	350.00	X
1 pc front o/s shock absorber	102.90	X
1 pc front o/s upper arm	1,185.70	X
1 pc front o/s lower arm	590.90	X
1 pc front o/s wheel bearing & hub	308.30	X
1 set steering tierodend	284.80	X
1 set steering rackend	119.20	X
1 pc air cond condenser (with fan motor, cowling, blade)	980.70	X
1 pc air cond condenser bracket	276.00	X
1 pc air cond suction hose	473.30	X
1 pc air cond dryer	137.00	X

- To remove & refix spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 25%

\$ 19,702.30
\$ 4,925.58
\$ 14,776.72

Towing charge (King Dolly)

120.00

To remove & refix dashboard, steering column shaft, air cond blower motor, brake master pump, pedal bracket & necessary parts.

380.00

To wiring check up & adjust headlight alignment.

80.00

To remove, refix air cond parts & refill R134 gas.

150.00

To remove & refix front windscreen glass.

120.00

To remove & refix front o/s shock absorber, lower arm, upper arm, bearing, steering tierodend, rackend & necessary parts.

300.00

To check & adjust front wheel alignment & balancing.

150.00

To remove & refix fuel tank, bracket & necessary parts.

150.00

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front centre cross member, front panel, wheel panel & necessary parts, to weld, renew & align above parts.

2,800.00

To respray Tuff-Kote on all affected accident parts.

150.00

To putty & respray painting on all affected accident parts.

2,400.00

\$ 21,426.72

Dollars : Twenty One Thousand Four Hundred Twenty Six And Cents Seventy Two Only.

HUP MOTOR TRADING & SERVICE

13085-55

P-11847.4
25%
P-8885-55
S-N-100
L-4100



WORKSHOP TRUCK NO. <i>1207</i>		meanour to your vehicles whilst being towed. 進行中如有任何損壞或破壞，一經由車主自行負責。The company accepts no responsibility for	
AMOUNT: <i>1207</i>		ID: 3. SCRATCHES 4. MISSING	
REMARKS: <i>acc</i> ☐ KING DOLLY ☐ ACCIDENT ☐ WAITING TIME ☐ JUMP START ☐ CHANGE/AMEND TYRE ☐ VEHICLE LOOKSMITH SERVICE ☐ MSCP/BASEMENT ☐ CRANE UP ☐ LOW BODYKIT ☐ COLLECTION OF KEY/DOCUMENT ☐ WINCH OUT		4(S) ON VEHICLE	
TO: <i>Ka Hing ref</i>		FROM: <i>GBK 6215B</i>	
MAKE/MODEL:		DATE: <i>28/11/17</i>	
INVOICE NO. SC 8187		Circle #12-130 Singapore 730721	
HOTLINE 9856 3360(KOP1)		mail.com	

Front : Left

Actual	Before	Specified Range
-0°30'	0°47'	-0°15' 1°15'
		2°25' 3°55'
0°00'	-0°31'	0°07' 0°12'
	0,0BAR	

Camber

Caster

Toe

SAI

Included Angle

Turning Angle Diff.

Tire Pressure

Front : Right

Actual	Before	Specified Range
-0°20'	-0°31'	-0°15' 1°15'
		2°25' 3°55'
0°00'	-0°28'	0°07' 0°12'
	0,0BAR	

Front

Cross Camber

Cross Caster

Cross SAI

Total Toe

Cross Turn Diff.

Actual	Before	Specified Range
-0°10'	1°18'	-0°30' 0°30'
		-0°30' 0°30'
		-0°30' 0°30'
0°00'	-0°59'	0°14' 0°24'

Rear : Left

Actual	Before	Specified Range
-0°08'	-0°08'	
0°14'	0°09'	
	0,0BAR	

Camber

Toe

Tire Pressure

Rear : Right

Actual	Before	Specified Range
-0°12'	-0°14'	
-0°15'	-0°11'	
	0,0BAR	

Rear

Cross Camber

Total Toe

Thrust Angle

Actual	Before	Specified Range
0°04'	0°06'	
-0°01'	-0°02'	
0°14'	0°10'	