

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Priya

Date: 01 Dec 2021

**Preliminary Advice**

Vehicle No	: GBK6215B	Accident Date	: 28/11/2021
Make	: TOYOTA DYNA 1.5T	Policy No.	: D21MCV0007106
Assignment Date	: 30/11/2021	Excess	: S\$0.00
Date of Inspection	: 30/11/2021	Est. Duration of Repair	: 10
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,426.72
Revised Amount	:S\$	11,401.60
Check Items (Estimated)	:S\$	3,717.98
Total	:S\$	15,119.58

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	22,067.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,933.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.