

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012111/AGA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210072707
Claimant Vehicle No :	SLF3378S	Insured Vehicle No :	GBD1951D
Date of Loss:	27/11/2021	Nature of Claim:	TP
		Claim No:	9038287560SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3378S	Engine No:	P520361680
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BM42A8G0339820
Reg. Date:	23/08/2016 (Man. Year: 2016)	Odometer:	84086 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,378.72	1,975.12	4,403.60	69.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,180.00	2,450.00	67.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,008.72	3,155.12	6,853.60	68.48
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	10,008.72	2,500.00	7,508.72	75.02
+ GST 7.00/7.00% (S\$)	700.61	175.00	525.61	75.02
Nett Amount (S\$)	10,709.33	2,675.00	8,034.33	75.02
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,932.45		
Global Sum Settlement (S\$)		2,930.00		

INSPECTION

Date of Assignment:	18/01/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	18/01/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR ASSY	Not Necessary	633.20 FL	*- FL
2	1		*FRONT SIDE MIRROR COVER	Cut	110.50 FL	*110.50 FL
3	1		*FRONT DOOR RH	Not Necessary	1,533.20 FL	*- FL
4	1		*SET FRONT DOOR STICKER	Not Necessary	90.00 FL	*- FL
5	1		*REAR DOOR RH	Dented	1,355.40 FL	*1,049.00 FL
6	1		*SET REAR DOOR STICKER	Necessary	90.00 FL	*90.00 FL
7	1		*REAR FENDER RH	Damaged	1,855.90 FL	*1,024.00 FL
8	1		*REAR WINDSCREEN MOULDING	Damaged	180.20 FL	*120.40 FL
9	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
10	1		*WHEEL TYRE	Not Necessary	380.00 FS	*- FS
11	1		*WHEEL RIM	Not Necessary	1,200.00 FS	*- FS
					Sub Total (\$)	7,548.40 2,453.90
					- List Item Discount on L Items 20.00/20.00% (\$)	1,169.68 478.78
					Total Parts (\$)	6,378.72 1,975.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,400.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	400.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX FRONT DOOR MECHANISM	New	100.00	0.00
6	REMOVE AND REFIX REAR DOOR MECHANISM	New	100.00	80.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	140.00	120.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$)			3,630.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >