

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS4/MSG21012112/BVF3E2

Date: 27/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29139692AT2
Claimant Vehicle No :	SNA9130C	Insured Vehicle No :	SKP5353J
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	639105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA9130C	Engine No:	CEH004030
Make & Model:	LAMBORGHINI GALLARDO LP550-2, 5.2 (A)	Chassis No:	ZHWGE52Z6BLA10245
Reg. Date:	11/11/2010 (Man. Year: 2010)	Odometer:	49459 km
Colour:	Black		
Engine Capacity:	5204 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	295/30 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,496.95	10,449.98	54,046.97	83.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	860.00	4,320.00	83.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	69,676.95	11,309.98	58,366.97	83.77
Approved Total (Overridden) (S\$)		9,050.00		
(S\$)	69,676.95	9,050.00	60,626.95	87.01
+ GST 7.00/7.00% (S\$)	4,877.39	633.50	4,243.89	87.01
Nett Amount (S\$)	74,554.34	9,683.50	64,870.84	87.01

INSPECTION

Date of Assignment:	01/12/2021	
Date Inspected:	30/11/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TP WITHDRAW CLAIM

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2022)
Parts:	M1-COUPE	LAMBORGHINI GALLARDO LP550-2 5.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA9130C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	8,926.00 FL	*5,440.00 FL
2	1		*REAR BUMPER GRILLE (DENTED)	Not Consistent With The Impact	5,848.00 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER COVER	Broken	3,521.00 FL	*2,927.40 FL
4	1		*REAR BUMPER RH NUMBER PLATE LAMP	Not Damaged	47.00 FL	*- FL
5	1		*REAR BUMPER LH NUMBER PLATE LAMP	Not Damaged	47.00 FL	*- FL
6	1		*REAR BUMPER RH SIDE BRACKET	Not Damaged	231.00 FL	*- FL
7	1		*REAR BUMPER LH SIDE BRACKET	Not Damaged	231.00 FL	*- FL
8	1		*REAR BUMPER RH EXHAUST PIPE FINISHERS	Not Damaged	1,283.00 FL	*- FL
9	1		*REAR BUMPER RH EXHAUST PIPE FINISHERS INNER BRACKET	Not Damaged	583.00 FL	*- FL
10	1		*REAR BUMPER LH EXHAUST PIPE FINISHERS	Cut	1,283.00 FL	*1,000.00 FL
11	1		*REAR BUMPER LH EXHAUST PIPE FINISHERS INNER BRACKET (BENT)	Not Consistent With The Impact	583.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	No such part	2,469.00 FL	*- FL
13	1		*ENGINE HOOD (BROKEN)	Not Consistent With The Impact	21,600.00 FL	*- FL
14	1		*ENGINE HOOD LAMBOORGHINI EMBLEM (NO SUCH PART)	Not Consistent With The Impact	322.00 FL	*- FL
15	1		*ENGINE HOOD LOCK CATCH	Not Damaged	31.00 FL	*- FL
16	1		*RH TAILLAMP ASSY (BROKEN)	Not Consistent With The Impact	3,441.00 FL	*- FL
17	1		*LH TAILLAMP ASSY (BROKEN)	Not Consistent With The Impact	3,441.00 FL	*- FL
18	1		*REAR END PANEL	Not Damaged	2,068.00 FL	*- FL
19	1		*EXHAUST SILENCER	Not Damaged	9,377.00 FL	*- FL
20	1		*EXHAUST SILENCER HEAT SHIELD (REAR)	Dented	399.00 FL	*250.00 FL
21	1		*EXHAUST SILENCER HEAT SHIELD (FRONT)	Not Damaged	399.00 FL	*- FL
22	1		*SET REAR BUMPER RIVETS	Not Necessary	100.00 FS	*- FS
23	1		*SET REAR BUMPER CLIPS	Not Necessary	120.00 FS	*- FS
24	1		*REAR BUMPER LOWER SPOILER COVER CLIPS	Necessary	100.00 FS	*30.00 FS
25	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
26	1		*REAR CENTRE EMBLEM PANEL	Cracked	1,351.00 FL	*1,351.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	67,871.00	10,998.40
- List Item Discount on L Items 5.00/5.00% (\$\$)	3,374.05	548.42
Total Parts (\$\$)	64,496.95	10,449.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	2,100.00	500.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,800.00	300.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	180.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL ENGINE HOOD WINDSCREEN GLASS TO ASSIST REPAIR	New	400.00	0.00
6	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	600.00	60.00
Gross Labour Cost (S\$)			5,180.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >