



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203635

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 13/06/2022  
Reference CC6/CTI21012113/Kea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SMG 5692D  
Insured Veh. SMK 8910J  
Claim No. SNM21D206887/C02  
Policy No. DMPCSNW00152992100  
Accident Date 26/11/2021  
Inspection Date 01/12/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21012113/Kea3q2	
			Date: 13/06/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMK 8910J	Veh. Inspected	SMG 5692D	
Policy No.	DMPCSNW00152992100	Coverage (\$)	0.00	
Claim No.	SNM21D206887/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZVW506050829	Colour	METALLIC GREY	
Odometer	262737 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	8 mm	
L/H Front Tyre	195/65 R15	SAILUN	8 mm	
R/H Rear Tyre	195/65 R15	APLUS	6 mm	
L/H Rear Tyre	195/65 R15	APLUS	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/11/2021	Inspection Date	01/12/2021	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 5692D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAILGATE 'PRIUS' EMBLEM	NECESSARY	61.75	61.75
1	REAR TAILGATE 'HYBRID' EMBLEM	NECESSARY	53.75	53.75
1	REAR TAILGATE 'TOYOTA' LOGO	NECESSARY	61.10	61.10
1	REAR TAILGATE OUTER GARNISH	MTG CRACKED	741.35	741.35
1	REAR TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	381.85	-
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	281.50	-
1	REAR BUMPER	BUCKLED	928.35	497.50
2	REAR BUMPER SIDE RETAINER @\$141.40	SERVICEABLE	282.80	-
1	REAR BUMPER DIFFUSER	DENTED	379.00	379.00
1	REAR BUMPER REINFORCEMENT	BENT	458.00	379.00
1	REAR BUMPER TOWING COVER	SERVICEABLE	61.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	970.25	-
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	381.90	381.90
1	REAR END PANEL SENSOR	CRACKED	281.50	281.50
	LESS 25% DISCOUNT		-1,331.03	-709.21
			3,993.07	2,127.64
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR PARKING SENSOR (SN)	SCRATCHED	280.00	200.00
1	SET REAR NUMBER PLATE & CASING (SN)	NECESSARY	50.00	45.00
			330.00	245.00
<b><u>LABOUR</u></b>				
	TUFFKOTE.	NOT NECESSARY	80.00	-
	WIRING.		80.00	15.00
	SPRAY PAINTING.		1,000.00	600.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE INNER LOCK AND REAR END PANEL .		1,000.00	400.00
			2,160.00	1,015.00
<b>GRAND TOTAL</b>			<b>6,483.07</b>	<b>3,387.64</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,700.00</b>
---	--	--	-----------------

Report Ref No. CC6/CTI21012113/Kea3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMG 5692D

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SMG 5692D**

**RE-INSPECTION**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMG 5692D

### RE-INSPECTION

