

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012116/KPA3Q2**Date:** 04/11/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1900151381-01 |
| Claimant Vehicle No : | SMZ2799A | Insured Vehicle No : | SMN3264H |
| Date of Loss: | 07/11/2021 | Nature of Claim: | TP |
| | | Claim No: | 6963131031SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMZ2799A | Engine No: | 2ZR2G83257 |
| Make & Model: | TOYOTA PRIUS, 1.8 (A) | Chassis No: | JTDKB3FU803091614 |
| Reg. Date: | 20/04/2021 (Man. Year: 2020) | Odometer: | 37560 km |
| Colour: | Metallic Silver | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Dunlop 3 mm | Rear Left Side: | Dunlop 2 mm |
| Front Right Side: | Dunlop 3 mm | Rear Right Side: | Dunlop 2 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,838.27 | 711.57 | 2,126.70 | 74.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,290.00 | 470.00 | 9,820.00 | 95.43 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 13,128.27 | 1,181.57 | 11,946.70 | 91.00 |
| + GST 7.00/7.00% (S\$) | 918.98 | 82.71 | 836.27 | 91.00 |
| Nett Amount (S\$) | 14,047.25 | 1,264.28 | 12,782.97 | 91.00 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 29/11/2021 | |
| Date Inspected: | 29/11/2021 | Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111 |
| Estimated Period of Repair: | 2.0 days | |

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|------------|------------|
| 1 | 1 | | *COVER ,REAR BUMPER | Buckled | 485.60 FL | *485.60 FL |
| 2 | 1 | | *REINFORCEMENT SUB-ASSY ,REAR BUMPER | *Check | 332.70 FL | *- FL |
| 3 | 1 | | *COVER ,REAR BUMPER LOWER | Dented | 22.00 FL | *22.00 FL |
| 4 | 1 | | *GUARD ,REAR BUMPER ,CENTER | Dented | 374.50 FL | *374.50 FL |
| 5 | 1 | | *RETAINER ,REAR BUMPER SIDE ,LH | Serviceable | 132.60 FL | *- FL |
| 6 | 1 | | *RETAINER ,REAR BUMPER SIDE ,RH | Serviceable | 132.60 FL | *- FL |
| 7 | 1 | | *COVER ,DECK TRIM ,REAR | Serviceable | 126.70 FL | *- FL |
| 8 | 1 | | *PANEL SUB-ASSY ,BODY LOWER BACK | Repair | 651.00 FL | *- FL |
| 9 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 10 | 1 | | *SET REAR BUMPER CLIP | Necessary | 95.00 FS | *50.00 FS |
| 11 | 1 | | *SET REAR BUMPER RETAINER CLIP | Not Necessary | 85.00 FS | *- FS |
| 12 | 1 | | *END PANEL TRIM CLIP | Not Necessary | 65.00 FS | *- FS |
| 13 | 1 | | *REAR NUMBER PLATE WITH MOULDING | Serviceable | 200.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|----------|--------|
| Sub Total (\$\$) | 3,402.70 | 932.10 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 564.43 | 220.53 |
| Total Parts (\$\$) | 2,838.27 | 711.57 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|------------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 300.00 | 0.00 |
| 2 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 3 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 2,200.00 | 200.00 |
| 4 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | New | 380.00 | 0.00 |
| 5 | TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 180.00 | 0.00 |
| 6 | TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR | New | 480.00 | 0.00 |
| 7 | TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 480.00 | 0.00 |
| 8 | TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACCUM AND CHARGE-IN-GAS | New | 380.00 | 0.00 |
| 9 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 10 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 11 | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 250.00 | 0.00 |
| 12 | TOWING FEES | New | 150.00 | 0.00 |
| 13 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 2,200.00 | 220.00 |
| 14 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 50.00 |
| 15 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 0.00 |
| 16 | TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 17 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 220.00 | 0.00 |
| 18 | TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR | New | 170.00 | 0.00 |
| 19 | TO LIFT -UP /OUT ENGINE WITH GEAR BOX AND REFIT | New | 440.00 | 0.00 |
| 20 | TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR | New | 380.00 | 0.00 |
| 21 | TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS | New | 380.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 10,290.00 | 470.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >