

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012122/KPA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100506310-04
Claimant Vehicle No :	SFQ18P	Insured Vehicle No :	GBF8801Y
Date of Loss:	27/11/2021	Nature of Claim:	TP
		Claim No:	7343482504SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFQ18P		
Make & Model:	MERCEDES-BENZ GLC300 SPORT, 2.0 4MATIC M-HYBRID (A)	Engine No:	26492080146061
Reg. Date:	30/09/2021 (Man. Year: 2021)	Chassis No:	W1N2533842F967208
Colour:	Metallic Blue	Odometer:	5806 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45Z R20	Rear Tyre Size:	285/40Z R20
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,817.10	492.30	2,324.80	82.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	60.00	1,920.00	96.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,797.10	552.30	4,244.80	88.49
Approved Total (Overridden) (S\$)		450.00		
(S\$)	4,797.10	450.00	4,347.10	90.62
+ GST 8.00/8.00% (S\$)	383.77	36.00	347.77	90.62
Nett Amount (S\$)	5,180.87	486.00	4,694.87	90.62
+ Loss of Use (0.5 x S\$100.00/day) (S\$)		50.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		538.00		

INSPECTION

Date of Assignment:	30/11/2021	
Date Inspected:	19/01/2022	Inspected At: Ding Auto Pte Ltd (HQ) 176 Sin Ming Drive #04-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	0.5 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	1,692.00 FL	*- FL
2	1		*FRONT BUMPER LOWER GRILLE	Serviceable	550.00 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP GARNISH	Dented	547.00 FL	*547.00 FL
4	1		*BUMPER SIDE LOWER GARNISH RHS	Serviceable	115.00 FL	*- FL
5	1		*BUMPER SIDE LOWER GARNISH LHS	Serviceable	115.00 FL	*- FL
6	1		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,119.00	547.00
- List Item Discount on L Items 10.00/10.00% (S\$)	301.90	54.70
Total Parts (S\$)	2,817.10	492.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & STRAIGHTEN -ACCIDENT AREA	New	500.00	60.00
2	SPRAY PAINT -FRONT BUMPER ,LOWER GRILLE & LOWER LIP GARNISH	New	1,000.00	0.00
3	REMOVE & INSTALL FRONT BUMPER COMPONENTS	New	250.00	0.00
4	ALIGN PARKING SENSOR AND CHECK WIRING	New	150.00	0.00
5	RUST PROOFING	New	80.00	0.00
			Gross Labour Cost (\$\$)	60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >